

REPORT OF SIGHTING/DISCOVERY

General locality _____

Date _____ Time _____

Approximate Position: Lat. _____ N.,

Long. _____ E.

Position Determined by (Method/Instrument used):

Nature/description of MSI (*Floating hazard, unlit light station,
uncharted shoals, adrift vessels etc.*)

Weather/sea condition in the locality _____

MSI Reported by:

Master or Navigator

Vessels/Country Registry

Enroute to: _____

To: The Director
Hydrography Branch
421 Barraca Street, San Nicolas
1010 Manila, PHILIPPINES
Fax No. (632) 242-20-90
E-mail: icsu_hd@namria.gov.ph



PHILIPPINE NOTICES TO MARINERS

Edition No. 10
31 October 2015

Notices Nos. 236 to 273

CONTENTS

- I Index of Charts affected
- II Notices to Mariners
- III NAVPhil Information

Produced by the Hydrography Branch

Published by the
Department of Environment and Natural Resources
NATIONAL MAPPING AND RESOURCE INFORMATION AUTHORITY

Notices to Mariners – Philippine edition are now on-line at
[http:// www.namria.gov.ph](http://www.namria.gov.ph) under the heading **Publication**

Subscription may be requested thru e-mail at oss@namria.gov.ph

GENERAL NOTICES

1. **NOTICES TO MARINERS** is a publication issued to mariners giving emphasis to changes in aids to navigation as well as recent charts correction data. It can be availed through a written application to the **Director, Hydrography Branch, NAMRIA, 421 Barraca Street, San Nicolas, 1010 Manila**. Copies may also be obtained directly from **NAMRIA** or other agencies distributing marine information. Digital format could be downloaded from **NAMRIA** Website: www.namria.gov.ph. or requested through E-mail address: oss@namria.gov.ph. An international service of centralization of Notices To Mariners exists in offices at various ports where national and certain foreign Notices To Mariners may be obtained. The Hydrography Branch of NAMRIA is the office of centralization in the Philippines.
2. The capital "P" or "T" affixed in the number of any notice denotes "*preliminary*" or "*temporary*", respectively. Asterisk " * " indicates that the information is based upon original Philippine source.
3. The codes of symbols in braces "[]" are referred to the INT 1 Publication of the International Hydrographic Organization (IHO).
4. All directions and bearings are measured clockwise from true North 000" to 360". Bearing on lights is based on the observer from seaward toward the light
5. The visibility assigned to the lights never exceeds the calculated distance at which they can be seen from a height of 4.57 meters above the level of the water at high tide.
6. Masters of vessels and other concerned are requested to advance any report of dangers to navigation and other information affecting Philippine Charts and Coast Pilots which may come to their attention to the **Director, Hydrography Branch, 421 Barraca Street, San Nicolas, 1010 Manila, Philippines**. If such information warrants urgent attention like for instance the non-existence of aids to navigation or failure of light beacons or similar structure or existence of floating mines, masters of vessels are requested to contact directly NAMRIA Radio Station DUS (free of charge) at 0800 and 1600 hours on weekdays and 0900 and 1600 hours on Saturdays. Station DUS transmits on 8484.0 KHz (Channel 1-CW) and 6363.0 KHz (Channel 2-CW). Contacts by landline may be had through telephone nos. (+632)245-0295, Facsimile nos. (+632)242-2090 and E-mail: icsu_hd@namria.gov.ph.
7. Changes in aids to navigation, their maintenance and correction of deficiencies in operation are under the operation of the Philippine Coast Guard. Report of defects and recommendations concerning aids to navigation should be forwarded to the Commandant, Philippine Coast Guard, Port Area, Manila, Philippines.
8. **WARNINGS:** Masters of vessels are warned that great care should be exercised in navigating Philippine waters because of the low visibility and occasional failure of some temporary lights. Buoys and beacons are sometimes lost or destroyed specially after typhoons. Temporary deficiencies in the standard aids to navigation published in this office may have been corrected before subsequent notice is issued.
9. Nautical Charts, Coast Pilot book, Topographic Maps, Tide and Current Tables and related publications are available for sale at the following NAMRIA Map Sales offices:

REQUEST FOR CORRECTIVE INFORMATION

Mariners are requested to notify the **Hydrography Branch, NAMRIA** of any changes or discrepancies found on Charts published by this office especially if this affect navigational safety in Philippine Waters. Reports may be sent by radio (see item # 6 General Notices), or by Facsimile (FAX No. (632) 242 20 90) or by speed mail to:

NAMRIA
Hydrography Branch
421 Barraca Street, San Nicolas
1010 Manila, Philippines
Attention: Maritime Affairs Division

Reports may also be sent by electronic mail (e-mail) to:
icsu_hd@namria.gov.ph

(Please send the information in format similar to that found at the back cover of this publication)

(Intentionally left as blank)

METRO MANILA:

NAMRIA, Taguig Main Office MSO

Fort Andres Bonifacio, Taguig City

Staff: Ms. Celeste Barile, Ph.D.

Contact Nos., (632) 810-4831 to 34 local 240, 810-5467, 0919-298990

San Nicolas, Manila MSO

Hydrography Branch

421 Barraca Street, San Nicolas, Manila

Staff: PO3 Samson Navidad

Contact Nos., (632) 241-3494 to 96 local 117, 245-9498, (0919)625-9276

DENR Central Office - MSO

Forest Management Bureau (FMB) Compound

Visayas Avenue, Quezon City

Staff: Ms. Alicia P. Ventura

Contact Nos., (632) 925-1157, (0915)543-3557

Region I – San Fernando, La Union MSO

DENR Government Center

Sevilla, San Fernando City

Staff: Ms. Bona G. Perez

Contact Nos., (072) 700-7957, (072) 242-6201, (0927)918-7175

Region II – Cagayan MSO

DENR – LEP, Building II

Carig, Tuguegarao City

Staff: Mr. Elias P. Bulaqui, Jr.

Contact Nos., (078) 846-7366, (078) 846-7347, (0921)676-8049

CAR – Baguio City MSO

Cottage I Forester Compound,

PACDAL, Baguio City

Staff: Mr. Conrado Labrador, Sr.

Contact Nos., (074) 442-5429, (074) 442-4531, (0918)920-3590

Region III – Central Luzon, Nueva Ecija MSO

GIS Room, WMRC Building,

Central Luzon State University Compound

Maharlika Highway, Muñoz City

Staff: Mr. Cielito Valino

Contact Nos., (044) 456-0690, (0917)931-3827

Region III – Central Luzon, Pampanga MSO

Diosdado Macapagal Government Center

Maimpis, San Fernando City

Staff: Ms. Lily Pineda

Contact Nos., (045) 963-4650, (045) 963-4646 or 49, (0921)316-6276

Region IVA – Southern Tagalog MSO

Provincial Planning and Development Office

Laurel Park, Capitol Site, Batangas City

Staff: Ms. Marcelita Aguda

Contact Nos., (043) 723-3286, (0919)975-0907

Region IVB – Puerto Princesa, Palawan MSO

DENR-PENRO Compound,

Brgy. Santa Monica, Puerto Princesa City

Staff: Ms. Wamalaída Talabucon

Contact Nos., (048) 433-5638, (048) 433-5639, (0918)370-2215

Region V – Bicol, Legaspi City MSO
DENR – Ecosystems Research and Development Service,
Kalikasan Park, Anahaw Village, Sagpon, Legaspi City
Staff: Ms. Isabelita Climaco
Contact Nos., (052) 481-1515, (052) 481-1542, 480-9825, (0919)894 4613

Region VI – Iloilo City MSO
DENR – Forestry Building,
Parola, Fort San Pedro, Iloilo City
Staff: Ms. Ma. Lucille Licaros
Contact Nos., (033) 336-5480, (033) 336-1013, (0918)386 5390

Region VII – Cebu City MSO
Room 301, Osmeña Building II,
Osmeña Boulevard, Cebu City
Staff: Ms. Rubi P. Lastimoso
Contact Nos., (032) 505-9945, (0915) 853 4498

Region VIII – Tacloban City MSO
DENR Compound,
Santo Niño Extension, Tacloban City, Leyte
Staff: Mr. Carmelo M. Cromente
Contact Nos., (053) 325-6223, (053) 321-3386, (0921) 362 8489

Region IX – Zamboanga City MSO
DENR CENRO WEST
General Vicente Alvarez St., Zone 4, Zamboanga City, Zamboanga del Sur
Staff: Ms. Magdalena Daraug
Contact Nos.: (062) 991 861279, (062) 991 2149, (062) 992 2484,

Region IX – Pagadian City, Zamboanga del Sur MSO
4th floor Pantaran Building
Rizal Avenue, Balingasan District, Pagadian City
Staff: Ms. Josefina Valdez
Contact No: (062) 215-4065

Region X – Cagayan de Oro City MSO
Day Care Center Building, DENR - Compound,
Macabalan (Puntod), Cagayan de Oro City, Misamis Oriental
Staff: Jennifer Bagamaspad
Contact Nos., (088) 856-9050, (088) 856-9591, (0919)266 8962

Region XI – Davao City MSO
FRCD Building, DENR - Compound
Lanang, Davao City, Davao del Sur
Staff: Eduardo Deocampo
Contact Nos., (082) 234-4401, (082) 234-7441, (0921) 668 5180

Region XII – SOCCKSARGEN, Koronadal City MSO
DENR Region 12, Land Evaluation Party Office,
Aurora Street, Koronadal City, South Cotabato
Staff: Ms. Rosalinda Balawang
Contact Nos., (083) 228-8476, (0921) 440 7141

CARAGA Region XIII – Butuan City MSO
Day Care Center Building, DENR Compound,
Ambago, Butuan City, Agusan del Norte
Staff: Mr. Rodeo L. Bonjoc
Contact Nos., (085) 342-6124, (085) 341-3250, (0910) 375 2616

III NAVPIL INFORMATION

Date: 03 November 2015

Reference No.: HD 164/15

MESSAGE

NAVPIL 069/15 – MINDANAO, S. COAST, DAVAO GULF – MARINE SURVEY

EGS ASIA INC., WILL CONDUCT A MARINE SURVEY FOR CABLE ROUTE ENGINEERING DESIGN ALONG DAVAO GULF. THE SURVEY WILL BE UNDERTAKEN BETWEEN 04 NOVEMBER 2015 AND 04 DECEMBER 2015 USING A VESSEL NAMED “MV GEMINI II” ON AREAS BOUNDED BY THE FOLLOWING COORDINATES:

POINT A	07° 01.908' N., 125° 31.870' E.
POINT B	07° 01.057' N., 125° 32.055' E.
POINT C	07° 01.352' N., 125° 33.804' E.
POINT D	07° 02.785' N., 125° 33.360' E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES.

III
NAVPHIL INFORMATION

Date: 13 October 2015

Reference No.: HD 155/15

MESSAGE

NAVPHIL 067/15 – PANAY, W. COAST – MARINE SURVEY

EGS ASIA INC., WILL CARRY OUT A MARINE SURVEY FOR CABLE ROUTE ALONG NEGROS-PANAY ISLAND. THE SURVEY WILL BE UNDERTAKEN BETWEEN 16 OCTOBER 2015 AND 30 NOVEMBER 2015 USING A VESSEL NAMED “GEMINI II” ON AREAS BOUNDED BY THE FOLLOWING COORDINATES:

POINT A	11° 00.52' N., 122° 50.55' E.
POINT B	11° 01.50' N., 122° 53.27' E.
POINT C	10° 54.20' N., 122° 59.08' E.
POINT D	10° 52.02' N., 122° 57.22' E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES.

Users may consult Notices to Mariners issued by the following foreign agencies for notices covering Philippine waters.

USA: National Geospatial & Intelligence Agency
Code GIMM, Mall Shop D-44
4600 Sangamore Road
Bethesda, MD 20816-5003
USA
<http://pollux.nss.ngamil>

United Kingdom: The United Kingdom Hydrographic Office
Admiralty Way
Taunton, Somerset, TA1 2DN,
UK
www.ukho.gov.uk

Japan: Hydrographic and Oceanographic Department
Japan Coast Guard
MLIT Aomi Building
2-5-18, Aomi, Koto-ku,
Tokyo 135-0064
Japan
<http://www1.kaiho.mlit.go.jp>

Australia: Royal Australian Navy
Hydrographic Service
161 Walker Street,
North Sydney, NSW, 2060
Australia
www.hydro.gov.au

I			
NUMERICAL INDEX OF CHARTS AFFECTED			
Charts No.	Notices Nos.	Charts No.	Notices Nos.
		4200	*10(247)15
			*10(248)15
1501	*10(264)15		*10(249)15
			*10(250)15
			*10(251)15
1535	*10(260)15		*10(252)15
	*10(261)15		*10(253)15
	*10(262)15		*10(254)15
			*10(255)15
			*10(256)15
1541	*10(255)15		*10(257)15
			*10(258)15
			*10(259)15
1542	*10(255)15		*10(260)15
			*10(261)15
			*10(262)15
1551	*10(248)15		*10(263)15
			*10(264)15
			*10(265)15
1552	*10(255)15		*10(266)15
			*10(267)15
			*10(268)15
			*10(269)T/15
			*10(270)T/15
		4210	*10(267)15
		4211	*10(237)15
			*10(266)15
			*10(267)15
			*10(270)T/15
		4212	*10(237)15
			*10(266)15
4200	*10(237)15		
	*10(238)15	4214	*10(265)15
	*10(239)15		
	*10(240)15		
	*10(241)15	4218	*10(254)15
	*10(242)15		*10(256)15
	*10(243)15		
	*10(244)15		
	*10(245)15	4220	*10(256)15
	*10(246)15		*10(257)15
			*10(260)15

III NAVPIL INFORMATION

Date: 08 September 2015

Reference No.: HD 140/15

MESSAGE

NAVPIL 061/15 – PHILIPPINE WATERS – HYDROGRAPHIC SURVEY

THE NATIONAL MAPPING AND RESOURCE INFORMATION AUTHORITY (NAMRIA) HYDROGRAPHY BRANCH, UTILIZING THE SURVEY VESSEL BRP HYDROGRAPHER HIZON, IS CURRENTLY CONDUCTING HYDROGRAPHIC SURVEY ACTIVITIES FROM 02 SEPTEMBER 2015 UNTIL 31 DECEMBER 2015 WITHIN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

VISAYAN SEA

- POINT A: 11° 53' 42"N., 123° 15' 24"E.
- POINT B: 11° 52' 24"N., 123° 28' 18"E.
- POINT C: 11° 23' 06"N., 124° 16' 42"E.
- POINT D: 11° 09' 12"N., 124° 21' 17"E.
- POINT E: 10° 55' 52"N., 124° 20' 38"E.
- POINT F: 10° 51' 39"N., 124° 26' 27"E.
- POINT G: 10° 46' 14"N., 124° 26' 27"E.
- POINT H: 10° 46' 48"N., 124° 15' 12"E.
- POINT I: 10° 47' 06"N., 124° 03' 06"E.
- POINT J: 11° 16' 36"N., 124° 04' 30"E.
- POINT K: 11° 40' 42"N., 123° 24' 12"E.
- POINT L: 11° 41' 48"N., 123° 14' 12"E.

(WGS84 DATUM)

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE THE NECESSARY PRECAUTIONARY MEASURES.

**III
NAVPHIL INFORMATION**

POINT 10: 09° 55' 34.7"N., 123° 19' 52.2"E.
 POINT 11: 09° 47' 53.1"N., 123° 20' 05.6"E.
 POINT 12: 09° 29' 52.5"N., 123° 17' 13.5"E.
 POINT 13: 09° 25' 07.0"N., 123° 17' 42.4"E.
 POINT 14: 09° 17' 43.6"N., 123° 27' 16.0"E.
 POINT 15: 09° 17' 50.1"N., 123° 20' 54.3"E.
 POINT 16: 09° 20' 36.0"N., 123° 19' 20.7"E.
 POINT 17: 09° 23' 36.2"N., 123° 16' 19.5"E.
 POINT 18: 09° 28' 36.4"N., 123° 14' 39.7"E.
 POINT 19: 09° 34' 22.4"N., 123° 11' 12.7"E.
 POINT 20: 09° 52' 49.8"N., 123° 10' 49.7"E.
 POINT 21: 10° 13' 43.8"N., 123° 20' 22.6"E.
 POINT 22: 10° 26' 18.2"N., 123° 27' 55.7"E.
 POINT 23: 10° 44' 00.7"N., 123° 33' 43.0"E.
 POINT 24: 11° 10' 43.6"N., 123° 51' 08.6"E.

(WGS84 DATUM)

ZONE C: CAMOTES SEA

POINT 1: 10° 47' 09.9"N., 124° 03' 07.8"E.
 POINT 2: 10° 46' 59.7"N., 124° 15' 09.7"E.
 POINT 3: 10° 32' 44.4"N., 124° 14' 56.1"E.
 POINT 4: 10° 32' 57.1"N., 124° 28' 12.9"E.
 POINT 5: 10° 25' 08.7"N., 124° 40' 30.3"E.
 POINT 6: 10° 16' 23.9"N., 124° 42' 49.8"E.
 POINT 7: 10° 22' 35.3"N., 124° 28' 27.8"E.
 POINT 8: 10° 19' 41.3"N., 124° 03' 34.7"E.

(WGS84 DATUM)

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE THE NECESSARY PRECAUTIONARY MEASURES.

I NUMERICAL INDEX OF CHARTS AFFECTED				
Charts No.	Notices Nos.		Charts No.	Notices Nos.
4220	*10(256)15		4313	*10(245)15
	*10(257)15			
	*10(260)15		4315	*10(248)15
				*10(251)15
4221	*10(252)15		4316	*10(240)15
	*10(253)15			*10(251)15
			4318	*10(240)15
4222	*10(253)15			
	*10(259)15		4325	*10(250)15
			4326	*10(242)15
4228	*10(268)15			*10(250)15
			4347	*10(242)15
4229	*10(268)15			
			4350	*10(246)15
				*10(247)15
4230	*10(263)15			
	*10(265)15		4351	*10(246)15
				*10(247)15
				*10(248)15
4235	*10(263)15			
			4357	*10(241)15
4236	*10(264)15		4412	*10(254)15
			4454	*10(255)15
4237	*10(252)15			
			4604	*10(261)15
				*10(262)15
4255	*10(237)15			
	*10(264)15		4608	*10(238)15
	*10(266)15			*10(239)15
	*10(267)15			
	*10(269)T/15		4624	*10(238)15
	*10(270)T/15			*10(239)15
			4639	*10(261)15
4258	*10(256)15			
			4705	*10(237)15
				*10(263)15
4305	*10(245)15			*10(264)15
	*10(248)15			*10(265)15
				*10(266)15
				*10(267)15
4309	*10(242)15			*10(269)T/15
	*10(249)15			
			4706	*10(237)15
4312	*10(244)15			*10(244)15

I			
NUMERICAL INDEX OF CHARTS AFFECTED			
Charts No.	Notices Nos.		Charts No.
4706	*10(245)15		4716
	*10(246)15		
	*10(247)15		
	*10(248)15		
	*10(251)15		
	*10(253)15		
	*10(254)15		
	*10(256)15	4718	
	*10(257)15		
	*10(258)15		
	*10(259)15	4720	
	*10(260)15		
	*10(264)15		
	*10(265)15		
	*10(266)15		
	*10(267)15		
	*10(269)T/15	4723	
	*10(270)T/15		
4707	*10(240)15		
	*10(241)15	4723A	
	*10(242)15		
	*10(243)15		
	*10(244)15		
	*10(249)15		
	*10(250)15		
4708	*10(238)15		
	*10(239)15	4726A	
	*10(252)15		
	*10(261)15		
	*10(262)15		
4714	*10(245)15		
	*10(246)15		
	*10(247)15		
	*10(248)15		
	*10(263)15		
	*10(264)15		
	*10(265)15		
	*10(270)T/15		
4715	*10(252)15		
	*10(253)15		
	*10(254)15		
	*10(255)15		
	*10(256)15		
	*10(257)15	4803	
	*10(258)15		
	*10(259)15		
	*10(260)15		

III

NAVPIL INFORMATION

Date: 08 September 2015

Reference No.: HD 139/15

No. of Pages: 2

MESSAGE

NAVPIL 060/15 – PHILIPPINE WATERS – HYDROGRAPHIC SURVEY

THE NATIONAL MAPPING AND RESOURCE INFORMATION AUTHORITY (NAMRIA) HYDROGRAPHY BRANCH, UTILIZING THE SURVEY VESSEL BRP HYDROGRAPHER PALMA, IS CURRENTLY CONDUCTING HYDROGRAPHIC SURVEY ACTIVITIES FROM 31 AUGUST 2015 UNTIL 31 DECEMBER 2015 WITHIN THE AREA BOUNDED BY THE FOLLOWING COORDINATES:

ZONE A: SIBUYAN SEA

POINT 1: 12° 13' 53.1"N., 122° 40' 50.8"E.
 POINT 2: 11° 53' 34.8"N., 123° 09' 04.3"E.
 POINT 3: 11° 53' 20.9"N., 123° 15' 45.5"E.
 POINT 4: 11° 41' 59.7"N., 123° 14' 29.7"E.
 POINT 5: 11° 43' 06.1"N., 123° 04' 10.3"E.
 POINT 6: 12° 04' 28.3"N., 122° 33' 56.8"E.

(WGS 84 DATUM)

ZONE B: TAÑON STRAIT

POINT 1: 11° 26' 47.9"N., 123° 47' 25.2"E.
 POINT 2: 11° 18' 46.3"N., 124° 01' 18.3"E.
 POINT 3: 11° 11' 33.1"N., 123° 54' 26.8"E.
 POINT 4: 11° 01' 47.8"N., 123° 53' 19.6"E.
 POINT 5: 10° 48' 46.5"N., 123° 50' 10.5"E.
 POINT 6: 10° 38' 18.1"N., 123° 44' 21.7"E.
 POINT 7: 10° 18' 29.9"N., 123° 33' 14.5"E.
 POINT 8: 10° 11' 50.1"N., 123° 31' 07.7"E.
 POINT 9: 10° 00' 08.3"N., 123° 21' 55.8"E.

Continue to next page

III
NAVPHIL INFORMATION

Date: 30 July 2015

Reference No.: HD 095/15

MESSAGE

**NAVPHIL 045/15 – LEYTE, W. COAST, ORMOC BAY –
HYDROGRAPHIC SURVEY**

THE NATIONAL MAPPING AND RESOURCE
INFORMATION AUTHORITY (NAMRIA) HYDROGRAPHY BRANCH
WILL CONDUCT HYDROGRAPHIC SURVEY AT PORT OF ORMOC
CITY, LEYTE AND VICINITY, UTILIZING NAMRIA SURVEY “SKIFF S-
JP-2”. THE SURVEY DURATION IS FROM 03 AUGUST UNTIL 30
NOVEMBER 2015 WITHIN THE AREA BOUNDED BY THE
FOLLOWING COORDINATES:

POINT	A	11° 01' 12.9733" N., 124° 31' 48.0231" E.
POINT	B	11° 01' 12.9733" N., 124° 37' 57.8778" E.
POINT	C	10° 52' 15.8105" N., 124° 37' 57.8778" E.
POINT	D	10° 52' 15.8105" N., 124° 31' 48.0231" E.

(WGS 84 DATUM)

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED
AREAS ARE ADVISED TO TAKE THE NECESSARY
PRECAUTIONARY MEASURES.

II
NOTICES TO MARINERS

***10(236)15 – Philippine NM, 30 September 2015, Edition No. 9 – Corrections**

***09(176)15** – Change Light's name from: **GUIMBONAN**, to: **GUIMBUNAN**

***09(181)15** – Replace Characteristics: **FI W 6s**, to: **FI W 5s**

***09(186)15** – Change International Number from: **F2174**, to: **F2714**

***09(190)15** – Replace: **4s, enclosed by 10m contour**, with: **4_{1/2}s, enclosed by 5fm contour**

***09(197)15** – Replace Characteristics from: **FI W 5s**, to: **FI (2) W 6s**
with: Characteristics from **FI W 5s** to **FI(2) W 5s**

***09(199)15** – Replace characteristics from: **FI (2) W 15s**, to: **FI W 5s**
with: characteristics from **FI (2) W 5s** to **FI W 5s**

***09(206)15** – Change Light's name from: **OLUTAYA LIGHT**, to: **OLUTAYA ISLAND LIGHT**

***09(212)15** – Change Light's name from: **WAWA LIGHT**, to: **WAWA LIGHTED BEACON**

***09(214)15** – Amend position from: **10° 39' 56" N., 122° 34' 08" E.**
to: **10° 39' 56.32" N., 122° 34' 08.43" E.** (WGS84 Datum)

***09(221)15** – Amend position from: **10° 28' 09" N., 123° 26' 54" E.**
to: **10° 28' 09.17" N., 123° 26' 53.64" E.** (WGS84 Datum)

NAMRIA Charts affected: 4200, 4323, 4334, 4707, 4716, 4720, 4723.
(PCG NM No.121 of 2015; H.D. 120/15, 125/15,135/15, 144/15)

***10(237)15 – LUZON, off E. COAST, Polillo Island, Burdeos – Light**

RIZAL LIGHT (F2747.64), restored to normal operation since 16 August 2015

Position : **15° 02' 31"N., 121° 58' 24"** [Luzon Datum]
Characteristics : **FI R 5s**

Note: This cancels Notice No. 09(204)15

NAMRIA Charts affected: 4200, 4226, 4275, 4705, 4726A
(PCG NM No. 113 of 2015; HD 135/15)

***10(238)15 – LUZON, W. COAST, Bataan, Mariveles – Light**

SISIMAN COVE LIGHT (F2631), reported operating since 07 August 2015

Position : **14° 25' 22.68"N., 120° 31' 11.54"E** [WGS 84]
Characteristics : **FI W 5s**

Note : This cancels Notice No. 09(213)15

NAMRIA Charts affected: 1501, 4200, 4211, 4255, 4705, 4706, 4714, 4726A
(PCG NM No. 113 of 2015; HD 135/15)

II
NOTICES TO MARINERS

***10(239)15 – LEYTE ISLAND, off S. COAST, Limasawa Island – Light**

NORTH LIMASAWA LIGHT(F2429), restored to normal operation with light characteristics changed since 26 August 2016.

Position : 09° 57' 58"N., 125° 03' 32"E [Luzon Datum]
Characteristics from : FI (2) W 8s to FI W 8s

Note : This cancels Notice No. 09(228)15

NAMRIA Charts affected: 4200, 4603, 4708, 4719, 1537
(PCG NM No. 121 of 2015; 144/15)

***10(240)15 – MINDANAO, S. COAST, Davao Gulf – Light**

PANACAN LIGHT(F2235), restored to normal operation since 12 August 2015.

Position : 07° 09' 10.26"N., 125° 39' 35.75"E [WGS 84]
Characteristics : FI G 5s

Note: This cancels Notice No. 09(231)15

NAMRIA charts affected: 4200, 4624, 4656, 4708
(PCG NM No. 121 of 2015; HD 144/15)

***10(241)15 – LUZON, W. COAST, Subic Bay – Navigational buoys**

Delete symbol, for **Main Traffic Lane East Lighted Buoy** at position
14° 47' 17.12"N, 120° 13' 57.12"E [WGS 84 Datum]

NAMRIA Charts affected: 4211, 4212, 4255, 4705, 4706, 4726A.
(SBMA email; H.D. 150/15)

***10(242)15 – MINDANAO, S. COAST, Davao Gulf – Buoys**

Insert symbol for **buoys** operated by Therma South Incorporated Power Plant with the following details:

- 1) **Name** : Intake Buoy 1
Position : 06° 57' 54.02" N., 125° 29' 12.78" E. [WGS 84]
Characteristics : FI Y 5s
Type of mark : Special Mark
Visibility : 5-7 Nautical miles
- 2) **Name** : Intake Buoy 2
Position : 06° 57' 55.73" N., 125° 29' 12.96" E. [WGS 84]
Characteristics : FI Y 5s
Type of mark : Special Mark
Visibility : 5-7 Nautical miles
- 3) **Name** : Outfall Buoy 1
Position : 06° 57' 48.37" N., 125° 29' 09.84" E. [WGS 84]
Characteristics : FI Y 5s
Type of mark : Special Mark
Visibility : 5-7 Nautical miles

III
NAVPHIL INFORMATION

Date: 07 April 2015

Reference No.: HD 043/15

MESSAGE

NAVPHIL 043/15 – PANAY, S. COAST, ILOILO STRAIT – BATHYMETRIC SURVEY

EGS ASIA INC., WILL CARRY OUT A PRE, MID, AND POST DREDGED BATHYMETRIC SURVEY IN ILOILO STRAIT SOUTH CHANNEL FOR A PROPOSED PORT. THE SURVEY WILL BE UNDERTAKEN BETWEEN 12 JULY 2015 AND 30 JANUARY 2016 USING THE LOCAL PASSENGER BANCA BASED IN ILOILO ON THE AREAS BOUNDED BY THE FOLLOWING COORDINATES:

POINT A	10° 39.00' N., 122° 31.40' E.
POINT B	10° 39.40' N., 122° 32.40' E.
POINT C	10° 38.30' N., 122° 32.70' E.
POINT D	10° 38.00' N., 122° 32.00' E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES.

II
NOTICES TO MARINERS

***10(271)15 – LUZON, N. COAST, Cagayan, Sta. Ana – Light**

PALAUIG LIGHT (F2682), restored to normal operation since 23 September 2015.

Position : 15° 25' 54" N., 119° 53' 52" E. [Luzon Datum]
Characteristics : FI (2) W 10s

NAMRIA Charts affected: 4200, 4228, 4229.
(PCG NM No.146 of 2015; H.D. 160/15)

***10(272)T/15 – LUZON, W. COAST, Manila Bay, Bulacan – Light**

BULACAN LIGHT (F2642.6), reported not operating since October 2015.

Position : 14° 42' 54" N., 120° 52' 12" E. [Luzon Datum]

NAMRIA Charts affected: 4200, 4255, 4705, 4706, 4726A.
(PCG NM No.146 of 2015; H.D. 160/15)

***10(273)T/15 – LUZON, Off W. COAST, El Fraile Island, Cavite – Light**

EL FRAILE LIGHT (F2635), reported not operating since August 2015.

Position : 14° 18' 24" N., 120° 37' 48" E. [Luzon Datum]

NAMRIA Charts affected: 4200, 4211, 4255, 4706, 4714, 4726A.
(PCG NM No.146 of 2015; H.D. 160/15)

II
NOTICES TO MARINERS

- 4) **Name** : Outfall Buoy 2
Position : 06° 57' 47.06" N., 125° 29' 09.15" E. [WGS 84]
Characteristics : FI Y 5s
Type of mark : Special Mark
Visibility : 5-7 Nautical miles
- 5) **Name** : Buoy A
Position : 06° 58' 18" N., 125° 29' 08.4" E. [Unknown Datum]
Characteristics : FI Y 4s
Type of mark : Special Mark
Visibility : 5-7 Nautical miles
- 6) **Name** : Buoy B
Position : 06° 57' 16.8" N., 125° 29' 09" E. [Unknown Datum]
Characteristics : FI Y 4s
Type of mark : Special Mark
Visibility : 5-7 Nautical miles
- 7) **Name** : Buoy C
Position : 06° 57' 08.40" N., 125° 29' 08.40" E. [Unknown Datum]
Characteristics : FI Y 4s
Type of mark : Special Mark
Visibility : 5-7 Nautical miles

NAMRIA Charts affected: 4608, 4624, 4708.
(PCG NM Nos. 131 and 132 of 2015; H.D. 152/15 and 153/15)

***10(243)15 – PALAWAN, Off W. COAST, Caccnipa Island – Light**

CACNIPA LIGHT (F2170), restored to normal operation since August 2015.

Position : 10° 30' 37" N., 119° 04' 19" E. [Unknown Datum]
Characteristics : FI (2) W 10s

NAMRIA Charts affected: 4200, 4316, 4318, 4707, 4716, 4723A.
(PCG NM No.140 of 2015; H.D. 154/15)

***10(244)15 – SULU SEA, Tubattaha National Park, South Islet – Light**

TUBATTAHA LIGHT (F2340), restored to normal operation since August 2015.

Position : 08° 44' 55.12" N., 119° 49' 11.05" E. [WGS84 Datum]
Characteristics : FI W 5s

NAMRIA Charts affected: 4200, 4357, 4707, 4716, 4723A.
(PCG NM No.140 of 2015; H.D. 154/15)

II
NOTICES TO MARINERS

***10(245)15 – BALABAC ISLAND, S. COAST, Cape Melville – Light**

CAPE MELVILLE LIGHT (*F2152*), restored to normal operation since August 2015.

Position : 07° 49' 06" N., 117° 00' 01" E. [Unknown Datum]
Characteristics : FI W 5s

NAMRIA Charts affected: 4200, 4309, 4326, 4347, 4707, 4720.
(PCG NM No.140 of 2015; H.D. 154/15)

***10(246)15 – PALAWAN, W. COAST, Rizal – Light**

TARUMPITAO LIGHT (*F2172*), restored to normal operation since August 2015.

Position : 09° 03' 30" N., 117° 38' 30" E. [Unknown Datum]
Characteristics : FI W 5s

NAMRIA Charts affected: 4200, 4707, 4718, 4720.
(PCG NM No.140 of 2015; H.D. 154/15)

***10(247)15 – PALAWAN, Off NE COAST, Manamoc Island – Light**

MANAMOC ISLAND LIGHT (*F2287*), restored to normal operation since August 2015.

Position : 11° 18' 20.28" N., 120° 40' 20.75" E. [WGS84 Datum]
Characteristics : FI (2) W 5s

NAMRIA Charts affected: 4200, 4312, 4706, 4707.
(PCG NM No.140 of 2015; H.D. 154/15)

***10(248)15 – PALAWAN, Off NE COAST, Bantac Island – Light**

BANTAC ISLAND LIGHT (*F2574.5*), restored to normal operation since August 2015.

Position : 12° 13' 15.67" N., 120° 23' 33.17" E. [WGS84 Datum]
Characteristics : FI (3) W 10s

NAMRIA Charts affected: 1552, 4200, 4305, 4313, 4706, 4714, 4723A, 4726A.
(PCG NM No.140 of 2015; H.D. 154/15)

II
NOTICES TO MARINERS

***10(267)15 – LUZON, W. COAST, Manila Bay, Manila Harbors – Light**

MANILA JETTY NR.2 LIGHT (*F2660.2*), restored to normal operation since October 2015.

Position: 14° 34' 15.30" N., 120° 57' 25.08" E. [WGS84 Datum]
Characteristics: FI R 5s

NAMRIA Charts affected: 1501, 4200, 4236, 4243, 4255, 4705, 4706, 4714, 4726A.
(PCG NM No.146 of 2015; H.D. 160/15)

***10(268)15 – LUZON, Laguna de Bay, Calamba – Light**

CALAMBA LIGHT (*F2651*), restored to normal operation since 14 September 2015.

Position: 14° 12' 45" N., 121° 11' 09" E. [Luzon Datum]
Characteristics: FI W 5s

NAMRIA Charts affected: 4200, 4214, 4230, 4705, 4706, 4714, 4726A.
(PCG NM No.146 of 2015; H.D. 160/15)

***10(269)15 – LUZON, W. COAST, Zambales, Subic– Light**

SUESTE POINT LIGHT (*F2673*), restored to normal operation since 16 September 2015.

Position: 14° 45' 09" N., 120° 11' 14" E. [Luzon Datum]
Characteristics: FI W 5s

NAMRIA Charts affected: 4200, 4211, 4212, 4255, 4705, 4706, 4726A.
(PCG NM No.146 of 2015; H.D. 160/15)

***10(270)15 – LUZON, Off W. COAST, Capones Island, Zambales – Light**

CAPONES LIGHT (*F2680*), restored to normal operation with light characteristics changed since 25 September 2015.

Position: 14° 55' 02" N., 120° 00' 27" E. [Luzon Datum]
Characteristics from: FI (3) W 5s **to:** FI (3) W 15s

NAMRIA Charts affected: 4200, 4210, 4211, 4255, 4705, 4706, 4726A, 4803.
(PCG NM No.146 of 2015; H.D. 160/15)

II
NOTICES TO MARINERS

***10(264)T/15 – MINDANAO, N. COAST, Dapitan – Light**

TAGOLO POINT LIGHT (F2282), reported not operating since 05 October 2015.

Position: 08° 43' 40" N., 123° 22' 43" E. [Luzon Datum]

NAMRIA Charts affected: 1535, 4200, 4604, 4639, 4708.
(PCG NM No.140 of 2015; H.D. 154/15)

***10(265)15 – MINDORO STRAIT, Apo Island and Reefs – Marine Protected Area**

Insert symbol, **N[20]**, for the limits of the core zone of Apo Reef Natural Park connected by the following positions:

- a) 12° 44' 47" N., 120° 27' 22" E.
- b) 12° 41' 11" N., 120° 33' 44" E.
- c) 12° 35' 47" N., 120° 29' 57" E.
- d) 12° 39' 18" N., 120° 23' 46" E., thence back to a)
[Luzon Datum]

Insert symbol **[N20]** for the limits of the **Buffer Zone** of the Apo Reef Natural Park connected by the following positions:

- e) 12° 46' 14" N., 120° 27' 00" E..
- f) 12° 41' 32" N., 120° 35' 19" E.
- g) 12° 34' 20" N., 120° 30' 16" E.
- h) 12° 38' 57" N., 120° 22' 12" E., thence back to e)
[Luzon Datum]

NAMRIA Charts affected: 1535, 4200, 4604, 4708, 4718.
(NAMRIA Report; H.D. 159/15)

***10(266)15 – LUZON, Laguna de Bay – Light**

NAPINDAN LIGHT (F2650), restored to normal operation since October 2015.

Position : 14° 31' 20" N., 121° 06' 53" E. [Luzon Datum]
Characteristics : FI R 5s

NAMRIA Charts affected: 4200, 4230, 4235, 4705, 4714, 4726A.
(PCG NM No.146 of 2015; H.D. 160/15)

II
NOTICES TO MARINERS

***10(249)15 – PALAWAN, N. COAST, Port Cullion – Light**

CULION ISLAND LIGHT (F2174), restored to normal operation since August 2015.

Position: 10° 53' 37" N., 120° 01' 22" E. [Unknown Datum]
Characteristics: FI R 5s

NAMRIA Charts affected: 4200, 4350, 4351, 4706, 4714, 4716, 4723A.
(PCG NM No.140 of 2015; H.D. 154/15)

***10(250)15 – CULION ISLAND, Off S. COAST, Dicabaito Island – Light**

DICABAITO ISLAND LIGHT (F2173), restored to normal operation since August 2015.

Position: 11° 38' 05" N., 119° 58' 04" E. [Unknown Datum]
Characteristics: FI (2) W 10s

NAMRIA Charts affected: 4200, 4350, 4351, 4706, 4714, 4716, 4723A.
(PCG NM No.140 of 2015; H.D. 154/15)

***10(251)15 – PALAWAN, Off N. COAST, Delian Island – Light**

DELIAN ISLAND LIGHT (F2176), restored to normal operation since August 2015.

Position: 11° 49' 44" N., 120° 18' 38" E. [Unknown Datum]
Characteristics: FI W 6s

NAMRIA Charts affected: 1551, 4200, 4305, 4315, 4351, 4706, 4714.
(PCG NM No.140 of 2015; H.D. 154/15)

***10(252)T/15 – PALAWAN, Off S. COAST, Mangsee Island – Light**

MANGSEE LIGHT (F2159), reported not operating since August 2015.

Position: 07° 30' 30" N., 117° 18' 18" E. [Unknown Datum]

NAMRIA Charts affected: 4200, 4309, 4707, 4720, 4723.
(PCG NM No.140 of 2015; H.D. 154/15)

***10(253)T/15 – PALAWAN, SE. COAST, Brooke's Point – Light**

BROOKE'S POINT JETTY LIGHT, Nr.2 (F2160.25), reported not operating since August 2015.

Position: 08° 46' 18" N., 117° 09' 36" E. [Unknown Datum]

NAMRIA Charts affected: 4200, 4325, 4326, 4707, 4716, 4720, 4723, 4723A.
(PCG NM No.140 of 2015; H.D. 154/15)

II
NOTICES TO MARINERS

***10(254)T/15 – PALAWAN, N. COAST, Port Cullion – Light**

CABULI LIGHT (F2169.2), reported not operating since August 2015.

Position : 11° 26' 30" N., 119° 30' 30" E. [Unknown Datum]

NAMRIA Charts affected: 4200, 4315, 4316, 4706, 4707, 4716, 4723A.
(PCG NM No.140 of 2015; H.D. 154/15)

***10(255)15 – LUZON, E. COAST, Tabaco – Light**

MALINAO RANGE (Front) LIGHT (F2802), restored to normal operation with light characteristics changed since 03 September 2015.

Position : 13° 24' 18" N., 123° 42' 48" E. [Luzon Datum]
Characteristics from : F R to: FI W 5s

NAMRIA Charts affected: 4200, 4221, 4237, 4708, 4715, 4726A.
(PCG NM No.140 of 2015; H.D. 154/15)

***10(256)15 – LUZON, Off E. COAST, Catanduanes Island – Light**

SIALAT POINT LIGHT (F2784), restored to normal operation with light characteristics changed since 01 September 2015.

Position : 13° 39' 51" N., 124° 01' 29" E. [Luzon Datum]
Characteristics from : FI W 4s to: FI W 5s

NAMRIA Charts affected: 4200, 4221, 4222, 4706, 4715, 4726A.
(PCG NM No.140 of 2015; H.D. 154/15)

***10(257)15 – MASBATE, Off N. COAST, Burias Island – Light**

PUNTA AGUJA LIGHT (F2503), restored to normal operation with light characteristics changed since 22 September 2015.

Position : 12° 41' 46" N., 123° 23' 00" E. [Luzon Datum]
Characteristics from : FI (3) W 10s to: FI W 10s

NAMRIA Charts affected: 4200, 4218, 4219, 4412, 4706, 4715, 4726A.
(PCG NM No.140 of 2015; H.D. 154/15)

***10(258)15 – BURIAS, N. COAST, Port Busing, San Pascual – Light**

SAN PASCUAL LIGHT (F2503.5), restored to normal operation with light characteristics changed since 22 September 2015.

Position : 13° 08' 52" N., 122° 59' 02" E. [Luzon Datum]
Characteristics from : FI W 10s to: FI W 5s

NAMRIA Charts affected: 1541, 1542, 4200, 4218, 4454, 4715, 4726A.
(PCG NM No.140 of 2015; H.D. 154/15)

II
NOTICES TO MARINERS

***10(259)15 – LUZON, SE. COAST, Calantas Rock – Light**

CALANTAS ROCK LIGHT (F2494), restored to normal operation since 27 August 2015.

Position: 12° 30' 43" N., 124° 04' 36" E. [Luzon Datum]
Characteristics: FI R 5s

NAMRIA Charts affected: 4200, 4219, 4220, 4258, 4706, 4715, 4726A.
(PCG NM No.140 of 2015; H.D. 154/15)

***10(260)15 – LUZON, SE. COAST, Balusingan Bay, Magdalena – Light**

MAGDALENA LIGHT (F2547), restored to normal operation with light characteristics changed since 26 August 2015.

Position: 12° 38' 18" N., 124° 05' 36" E. [Luzon Datum]
Characteristics from: FI (2) W 10s to: FI W 5s

NAMRIA Charts affected: 4200, 4220, 4706, 4715, 4726A.
(PCG NM No.140 of 2015; H.D. 154/15)

***10(261)T/15 – LUZON, S. COAST, Camarines Sur – Light**

LAGANAC LIGHT (F2504), reported not operating since 25 September 2015.

Position: 13° 20' 36" N., 123° 12' 42" E. [Luzon Datum]

NAMRIA Charts affected: 4200, 4218, 4706, 4715, 4726A.
(PCG NM No.140 of 2015; H.D. 154/15)

***10(262)T/15 – LUZON, E. COAST, Caramoan Peninsula – Light**

GIBGOS LIGHT (F2778.7), reported not operating since August 2015.

Position: 13° 51' 36" N., 123° 46' 06" E. [Luzon Datum]

NAMRIA Charts affected: 4200, 4222, 4706, 4715, 4726A.
(PCG NM No.140 of 2015; H.D. 154/15)

***10(263)T/15 – LUZON, SE. COAST, San Bernardino Island – Light**

SAN BERNARDINO LIGHT (F2488), reported not operating since August 2015.

Position: 12° 45' 15" N., 124° 16' 57" E. [Luzon Datum]

NAMRIA Charts affected: 4200, 4220, 4706, 4715, 4726A.
(PCG NM No.140 of 2015; H.D. 154/15)