



Republic of the Philippines
Department of Environment and Natural Resources
National Mapping and Resource Information Authority
Hydrography Branch
421 Barraca Street, San Nicolas
Manila, Philippines

Date: 04 December 2015

Reference: PCG MC 02-15 (HD 113/15)

Subject: NAVPHIL.INFORMATION

No. of Pages: 2

MESSAGE

NAVPHIL 082/15 – PUERTO PRINCESA HARBOR – ANCHORAGE & BUOYS

THE PHILIPPINE COAST GUARD ESTABLISHED AN ANCHORAGE AREA FOR FOREIGN VESSELS DESCRIBED BY THE FOLLOWING COORDINATES (LUZON DATUM):

	Latitude	Longitude
A	09° 43' 34" N	118° 43' 16" E
B	09° 43' 06" N	118° 43' 42" E
C	09° 42' 52" N	118° 43' 30" E
D	09° 43' 16" N	118° 43' 05" E

BUOYS WERE ALSO REPORTED TO EXIST AT THE FOLLOWING POSITIONS (LUZON DATUM):

	Latitude	Longitude
Shell Depot Mooring Buoy 1	09° 43' 53" N	118° 43' 41.9" E
Shell Depot Mooring Buoy 2	09° 43' 51.5" N	118° 43' 46.7" E
Shell Depot Mooring Buoy 3	09° 43' 53.9" N	118° 43' 48" E
Shell Depot Mooring Buoy 4	09° 43' 56" N	118° 43' 44.2" E
Fairway Buoy	09° 42' 22.40" N	118° 46' 10.52" E

THIS WARNING SERVES AS CORRECTION TO NOTICE NO. 09(170)15. A NOTICE TO MARINERS WILL BE ISSUED TO FULLY AMEND THE AFOREMENTIONED NOTICE.

Page 1 of 2

Please advise by phone/fax if any part of this message is not received



NAMRIA OFFICES:

Main : Lawton Avenue, Fort Bonifacio, 1634 Taguig City, Philippines Tel. No.: (632) 810-4831 to 41


Branch : 421 Barraca St. San Nicolas, 1010 Manila, Philippines, Tel. No. (632) 241-3494 to 98

www.namria.gov.ph

ISO 9001:2008 CERTIFIED FOR MAPPING AND GEOSPACIAL INFORMATION MANAGEMENT

ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE THE NECESSARY PRECAUTIONARY MEASURES.

Hydrography Branch
 (C) Barrera Street, San Nicolas
 Manila, Philippines



Commodore JACINTO M CABLAYAN
 Director

Date: 04 December 2015

Subject: NAVPHILINFORMATION

MESSAGE

NAVPHIL 00216 - PUERTO PRINCIPERA HARBOR - ANCHORAGE & BUOYS

Page 2 of 2

THE PHILIPPINE COAST GUARD ESTABLISHED AN ANCHORAGE AREA FOR FOREIGN VESSELS DESCRIBED BY THE FOLLOWING COORDINATES (LUZON DATUM):

	Latitude	Longitude
A	09° 43' 34" N	118° 43' 18" E
B	09° 43' 06" N	118° 43' 42" E
C	09° 42' 22" N	118° 43' 38" E
D	09° 43' 16" N	118° 43' 05" E


SUOYS WERE ALSO REPORTED TO EXIST AT THE FOLLOWING POSITIONS (LUZON DATUM):

	Latitude	Longitude
Shell Depot Mooring Buoy 1	09° 43' 53" N	118° 43' 41.8" E
Shell Depot Mooring Buoy 2	09° 43' 51.5" N	118° 43' 48.7" E
Shell Depot Mooring Buoy 3	09° 43' 53.5" N	118° 43' 48" E
Shell Depot Mooring Buoy 4	09° 43' 58" N	118° 43' 44.2" E
Fairway Buoy	09° 42' 22.49" N	118° 48' 18.62" E

THIS WARNING SERVES AS CORRECTION TO NOTICE NO. 09/170/15. A NOTICE TO MARINERS WILL BE ISSUED TO FULLY AMEND THE AFOREMENTIONED NOTICE.

Page 1 of 2

Please advise by phone fax if any part of this message is not received



NAVPHIL 00216
 Date: 04 December 2015
 (C) Barrera Street, San Nicolas, Manila, Philippines
 Tel. No. 822 21 261 to 21
 Fax No. 822 21 261 to 21
 www.navphil.mil.ph
 THE PHILIPPINE COAST GUARD AND HYDROGRAPHIC INFORMATION AUTHORITY