

Republic of the Philippines **Department of Environment and Natural Resources** NATIONAL MAPPING AND RESOURCE INFORMATION AUTHORITY www.namria.gov.ph

Date: 07 February 2022 Reference: PCG NTM 028 - 2022

(HD 025/22)

Subject: NAVPHIL.INFORMATION No. of Pages: 1

MESSAGE

NAVPHIL 019/22 - CEBU, E. COAST, CEBU HARBOR - UNLIT BUOYS

THE FOLLOWING BUOYS WERE REPORTED UNLIT:

NAME OF BUOY	POSITION
CB-D	10° 14' 06"N., 123° 53' 02"E.
CB-2	10° 14' 06"N., 123° 53' 13"E.
Lipata Bank Isolated Danger Mark	10° 14' 29"N., 123° 52' 37"E.
Narvaez Reef Isolated Danger Mark	10° 14' 44"N., 123° 52' 04"E.
Cauit Isolated Danger Mark	10° 16' 22"N., 123° 53' 09"E.
Banilad Shoal Isolated Danger Mark	10° 18' 39"N., 123° 55' 55"E.
Cebu Channel Lighted Buoy No. 10	10° 19' 56"N., 123° 58' 23"E.
Cebu Channel Lighted Buoy No. 3	10° 20' 39"N., 124° 00' 10"E.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE-MENTIONED AREAS ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

Officer-in-Charge, Hydrography Branch

