



Date: 13 July 2021

Reference: PCG NTM 183-2021
(HD 141/21)

Subject : NAVPHIL.INFORMATION

No. of Pages: 1

MESSAGE

NAVPHIL 117/21 – PANAY, SE. COAST, GUIMARAS STRAIT – MISSING BUOYS

THE FOLLOWING BUOYS WERE REPORTED MISSING AT THE FOLLOWING COORDINATES:

| | POSITION |
|----------------------------------|--------------------------------------|
| ILOILO NORTH CHANNEL BUOY | 10° 45' 07"N., 122° 38' 35"E. |
| TSS-BAC B BUOY | 10° 41' 30"N., 122° 55' 24"E. |

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE-MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES AT ALL TIMES.

Commander ANTONIO G VALENZUELA JR
Officer-in-Charge, Hydrography Branch

Please e-mail maritime.affairs@namria.gov.ph if any part of this message is not received

NAMRIA OFFICES:

☎ Lawton Avenue, Fort Bonifacio, 1634 Taguig City, PH ☎ (632) 8810-4831 to 41
☎ 421 Barraca St., San Nicolas, 1010 Manila, PH ☎ (632) 8241-3494 to 98



ISO 9001:2015
CERTIFIED FOR MAPPING
AND GEOSPATIAL
INFORMATION MANAGEMENT

INVESTORS IN PEOPLE™
We invest in people Silver