



Date: 12 January 2017

Reference: EGS Asia Report  
(HD 010/17)

Subject: NAVPHIL.INFORMATION

No. of Pages: 1

**MESSAGE**

**NAVPHIL 003/17 – PANAY SE. COAST, ILOILO STRAIT – BUOYS**

**PANAY ENERGY DEVELOPMENT CORP. RECENTLY INSTALLED FOUR NAVIGATIONAL BUOYS, WHICH MARK THE LIMITS OF THE DREDGED AREA IN THE SOUTHERN CHANNEL TO ILOILO HARBOR, AT THE FOLLOWING COORDINATES:**

**BUOY 1: 10° 38.6516' N., 122° 32.4592' E.  
BUOY 2: 10° 38.6525' N., 122° 32.5590' E.  
BUOY 3: 10° 38.2324' N., 122° 32.5415' E.  
BUOY 4: 10° 38.2281' N., 122° 32.4478' E.  
(WGS84 DATUM)**

**THE ABOVE MENTIONED BUOYS REPLACED THE TEMPORARY BUOYS REPORTED IN NAVPHIL 056/16 AND NAVPHIL 058/16.**

**ALL SHIPS/WATERCRAFTS TRANSITING THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE THE NECESSARY PRECAUTIONARY MEASURES.**

  
**Commodore JACINTO M CABLAYAN**  
Director

*Please advise by phone/fax if any part of this message is not received*

