



Date: 15 August 2018

Reference: SBMA Seaport Dept. eMail
(HD 205/18)

Subject : NAVPHIL.INFORMATION

No. of Pages: 1

MESSAGE

NAVPHIL 115/18 – LUZON, W. COAST, SUBIC BAY –BUOY

NAVIGATIONAL BUOY Nr. 13, AT POSITION 14° 48' 31.39"N., 120° 14' 13.91"E., HAS BEEN REPORTED DRIFTED AND SECURED IN ONE OF PORT FACILITIES LAST 13 AUGUST 2018.

TO DATE, 17 OUT OF 21 NAVIGATIONAL BUOYS ARE OUT OF ITS DESIGNATED LOCATION (BUOY Nr. 1, 2, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17 AND 21).

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES.

Commodore JACINTO M CABLAYAN
Director, Hydrography Branch

Please advise by phone/fax if any part of this message is not received



NAMRIA OFFICES:

Main : Lawton Avenue, Fort Bonifacio, 1634 Taguig City, Philippines Tel. No.: (632) 810-4831 to 41
Branch : 421 Barraca St. San Nicolas, 1010 Manila, Philippines, Tel. No. (632) 241-3494 to 98

www.namria.gov.ph

ISO 9001:2008 CERTIFIED FOR MAPPING AND GEOSPACIAL INFORMATION MANAGEMENT