



PHILIPPINE NOTICES TO MARINERS

Monthly Edition No.: 2024-11
30 November 2024

Notices Nos.: 111 to 115

CONTENTS

- I Index of Charts Affected
 - II Chart Corrections
 - III Temporary & Preliminary Notices
 - IV List of Lights Corrections
 - V Coast Pilot Corrections
 - VI Navigational Warnings
 - VII Publication Notices
-

Published by
National Mapping and Resource Information Authority
Lawton Avenue, Fort Bonifacio, Taguig City

ISSN 3028 -1067

Tel: (632) 8241-3494 to 98
Email: csu.hb@namria.gov.ph (NAMRIA Client Service Unit)
Website: www.namria.gov.ph

MARITIME AFFAIRS DIVISION
Maritime Spatial and Safety Information Service
Editorial Board 2024

Editors-In-Chief:

CDR LORENA JASMIN D LERIO
LT MAY ANNE L JAVIER

Supervising Editor:

ENS GEORGE L DIMEN JR

Verifier:

HERMIELYN C. SAGUCIO

Compilers:

SN3 ANJANETTE A CRUCIS
SN3 RHEAN MARK A MONILLA
SN3 SAMUEL F SORIANO
ROVILLA R. QUIMING
TERESITA B. SARMIENTO

THE PHILIPPINE NOTICES TO MARINERS is a monthly publication produced by the National Mapping and Resource Information Authority (NAMRIA). It contains the recent chart corrections, updates to nautical publications, and other information that is vital for the safety of navigation on Philippine waters.

Copies in digital format may be obtained or by downloading at the NAMRIA website: <https://namria.gov.ph/downloads.aspx#publications> or by sending a request through the email address maritime.affairs@namria.gov.ph.

Organized chart corrections, cumulative and summary list of chart corrections as well as online hydrographic note are also available through the **Online Maritime Safety Information System (OMSIS)**, <https://isportal.namria.gov.ph/OMSIS/Default.aspx>

Masters of vessels and other concerned parties are requested to advance any report of dangers to navigation and other information affecting Philippine Charts and Coast Pilots, which may come to their attention, to the **Director, Hydrography Branch**. If such information warrants urgent attention, for instance the non-existence of aids to navigation or failure of light beacons or similar structures or discovery of new shoals, all concerned are requested to contact NAMRIA directly through the following portals:


Mail	NAMRIA Hydrography Branch, 421 Barraca St San Nicolas, 1010 Manila, Philippines
E-mail	maritime.affairs@namria.gov.ph
Landline	(+632) 8245-0295
Online	https://namria.gov.ph/omsis/HNNote10.aspx .

Active navigational warnings are accessible at <https://staging.geoportal.gov.ph/nwapp/>

EXPLANATORY NOTES

- The Philippine Notices to Mariners is divided into the following sections:

Section I. Index of Charts Affected – Contains the list of all nautical charts which have been affected by Notices to Mariners and the Notice Numbers which have affected them.



Section II. Chart Corrections - Contains corrections to nautical charts in sequential numbers with the indication of the month and year of its issuance. The illustration below describes the elements that comprise a typical notice:

Notice No. preceded by an asterisk “ * ” indicates that the information is based upon the original Philippine source.

Section III. Temporary & Preliminary Notices – Contains Notices to Mariners that temporarily affect the nautical charts or have preliminary information that is subject to further verification. The capital “P” or “T” affixed in the number of any notice denotes “preliminary” or “temporary”, respectively.

A list of Temporary and Preliminary Notices that are still in force is published in this publication every month. The list may be read on Page v.

Section IV. List of Lights Corrections – Contains the corrections to the latest edition of the Philippine List of Lights. The entire entry for each light will be printed and the columns that contain updates will be denoted by an asterisk “ * ”. All columns will be denoted by asterisks in the case of new lights.

This section is intended to be printed, cut out and pasted on the section of the List of Lights that is being corrected.

All updates to lighted aids, including their operational status, will be published in this section. All directions and bearings are measured clockwise from True North 000° to 360°. Bearing on lights is based on the observer from seaward toward the light. The visibility assigned to the lights never exceeds the calculated distance at which they can be seen from a height of 4.57 meters above the level of the water at high tide.

Changes in aids to navigation, their maintenance, and correction of deficiencies in operation are under the operation of the Philippine Coast Guard. Report of defects and recommendations concerning aids to navigation should also be forwarded to the Commandant of the Philippine Coast Guard.

Section V. Coast Pilot Corrections – Contains the corrections to the latest editions of the Philippine Coast Pilot books.

Section VI. Navigational Warnings – Contains the reprints of all previously issued navigational warnings that are still in effect as of the publication date of this edition of the Philippine Notices to Mariners.

Section VII. Publication Notices – Contains the latest updates on the nautical charts, electronic navigational charts, and other nautical publications of NAMRIA.

2. NAMRIA issues Notices to Mariners and Navigational Warnings sourced from private entities, foreign publications, national government agencies, and local government units. Such information is published for the sake of the safety of navigation on Philippine waters and does not imply recognition of the legal validity of the information issued by the abovementioned sources.
3. While every effort is made to ensure the accuracy of NAMRIA nautical charts and publications, users should bear in mind that it may not be complete or up-to-date, especially in areas where there are extensive developments. Mariners are advised to exercise prudence and to also refer to all navigational equipment aboard the ship and use a lookout during navigation.
4. Masters of vessels are warned that great care should be exercised in navigating Philippine waters because of the low visibility and occasional failure of some navigational lights. Buoys and beacons are sometimes lost or destroyed, especially after typhoons. Temporary deficiencies in the standard aids to navigation published in this office may have been corrected before subsequent notice is issued.
5. Positions obtained from satellite navigation systems, such as GPS, are normally referred to the WGS-84 Datum. Such position may only be plotted on NAMRIA nautical charts that are also referred to the WGS-84 Datum. Mariners should take note that due to the age and quality of some of the information, such satellite-derived positions may be more accurate than charted details.

List of Temporary and Preliminary Notices

(in force as of 30 November 2024)

11(115)T/24 BATANES GROUP OF ISLANDS, Batan Island – Light
10(110)T/24 LUZON, W. Coast, Manila Bay – Wreck. Restricted Area
10(109)T/24 LUZON, W. Coast, Manila Bay - Buoy
10(108)T/24 DAVAO, NE. Coast, Pakiputan Strait - Buoys
09(101)P/24 LUZON, W. Coast, Zambales – Dredging
09(100)P/24 LUZON, W. Coast, Manila Bay – Reclamation
08(092)T/24 WEST PHILIPPINE SEA, Julian Felipe Reef - Buoys
08(091)T/24 LUZON, S. Coast, Odiongan Bay - Buoy
08(090)T/24 LEYTE, S. Coast, San Juan - Lights
08(089)T/24 LEYTE, N. Coast, Biliran I – Light
08(088)T/24 SAMAR, W. Coast, - Lights
08(087)T/24 SAMAR, NE. Coast, Hiuinatungan I - Light
08(086)T/24 KALAYAAN ISLAND GROUP, Pag-asa Island – Buoy
07(074)T/24 PALAWAN, N. COAST, Cabuli I. - Light
07(073)T/24 LUZON, S. COAST, Sibuyan I - Lights
07(072)T/24 LUZON, NE. COAST - Lights
07(071)T/24 PHILIPPINE RISE, Benham Bank - Buoys
07(070)T/24 PALAWAN, N. COAST, Coron Passage - Buoys
07(069)T/24 LUZON, S. COAST, Sibuyan Island - Lights
07(068)T/24 LUZON, S. COAST, Laguna de Bay - Lights
07(067)T/24 LUZON, N. COAST, Batan Island-Light
07(066)T/24 LUZON, W. COAST, Manila Bay – Anchorage
07(065)T/24 LUZON, NE. COAST, Padsan River - Dredging
09(114)P/23 LUZON. S. COAST, Batangas Bay - Terminal
03(048)T/23 PALAWAN, E. COAST, off Miniloc island - Buoy
03(047)T/23 BOHOL, W. COAST, Dawahon Bank – Light
02(032)T/23 PALAWAN, N. COAST, Coron Bay – Buoy
02(031)T/23 LUZON, W. COAST, Manila Bay – Buoy
01(020)T/23 LUZON, W. COAST, Manila Bay - Buoy
12(077)T/22 MASBATE, NORTH COAST, Masbate Harbor - Beacon
09(040)T/22 LUZON, W. COAST, Manila Bay – Buoy
07(032)T/22 LUZON, W. COAST, Manila Bay – Buoy
07(031)T/22 LUZON, W. COAST, Manila Bay – Buoy
05(022)T/22 LUZON, W. COAST, Manila Bay – Buoy
02(006)T/22 LUZON, W. COAST, Manila Bay – Buoys
04(023)P/19 MINDANAO,N. COAST, Iligan Bay – Buoy
02(014)P/17 MINDANAO,N. COAST, Butuan Bay – Submarine Pipeline

TABLE OF CONTENTS

Index of Charts Affected - - - - -	01
Chart Corrections - - - - -	02
Temporary & Preliminary Notices - - - - -	04
List of Lights Corrections - - - - -	05
Coast Pilot Corrections - - - - -	06
Navigational Warnings - - - - -	07
Publication Notices - - - - -	10

I
INDEX OF CHARTS AFFECTED

Chart No	Notice No.	Chart No	Notice No.	Chart No	Notice No.	Chart No	Notice No.
1506	11(115)T/24	4280	11(115)T24	4723B	11(114)24	PH2NLZ40	11(111)24
1507	11(115)T/24	4338	11(113)24	4726A	11(111)24 11(115)T/24	PH2CVZ40	11(112)24 11(113)24 11(114)24
1515	11(112)24	4705	11(115)T/24	5001	11(115)T24	PH3DALUP	11(115)T/24
1551	11(114)24	4706	11(114)24	5002	11(111)24		
1564	11(113)24	4707	11(114)24	5008	11(113)24 11(114)24		
2200	11(111)24 11(114)24 11(115)T/24	4714	11(113)24				

II

CHART CORRECTIONS

***11(111)24 – PHILIPPINE SEA, Talampas ng Pilipinas - Geographic Name**

Chart 2200 1Ed 08/28/2020 [WGS-84 DATUM] Last NM 08(084)24

Amend, Geographic name from Philippine Rise to Talampas ng Pilipinas

at 16°09.3'N 123°39.0'E

Chart 4726A 4Ed 01/30/2018 [WGS-84 DATUM] Last NM 09(099)24

Amend, Geographic name from Philippine Rise to Talampas ng Pilipinas

at 16°16.1'N 123°48.3' E

Chart 5002 1Ed 13/02/2024 [WGS-84 DATUM] Last NM 08(081)24

Amend, Geographic name from Philippine Rise to Talampas ng Pilipinas

at 16°32.0'N 124°15.4'E

ENCs Affected: PH2NLZ40
(Malacañang)

***11(112)24 – LUZON, SE. Coast, Sorsogon - Geographic Name**

Chart 1515 1Ed 02/29/2012 [WGS-84 DATUM] Last NM 09(099)24

Amend, Geographic name from Tiguib to Quirapi

at 12°52.56'N 123°46.53'E

Insert, Geographic name Bagalayag

at 12°56.31'N 123°52.30'E

ENCs Affected: PH2CVZ40
(Philippine Statistics Authority)

***11(113)24 – MINDORO, NW. Coast, Lubang Island - Geographic Name**

Chart 1564 2Ed 02/02/2012 Rev 11/29/2021 [WGS-84 DATUM] Last NM 09(094)24

Amend, Geographic name from Manog Pt to Manok Pt

at 13°40.28'N 120°16.06'E

Chart 4338 1Ed 10/17/1959 Rev 01/5/1976 [Luzon Datum] Last NM 05(067)23

Amend, Geographic name from Manog Pt to Manok Pt

at 13°40'20"N 120°16'10"E

Chart 4714 1Ed 09/1959 Rev 03/1986 [Luzon Datum] Last NM 07(054)24

Amend, Geographic name from Manog Pt to Manok Pt

at 13°40.3'N 120°16.1'E

Chart 5008 1Ed 02/15/2024 [WGS-84 DATUM] Last NM 10(105)24

Amend, Geographic name from Manog Pt to Manok Pt

at 13°40.4'N 120°16.1'E

ENCs Affected: PH2CVZ40
(NAMRIA)

***11(114)24 – PALAWAN, E. Coast, Manamoc Island – Light**

Chart 1551 3Ed 02/28/2024 [WGS84 Datum] Last NM 11(122)23

Amend light characteristics of Manamoc Island light from Fl(2)W 5s to Fl.10s

at 11°18.33N 120°40.35E

II CHART CORRECTIONS

***11(114)24 – PALAWAN, E. Coast, Manamoc Island – Light**

(continued)

Chart 2200 1Ed 08/28/2020 [WGS84 Datum] Last NM 11(111)24

Insert



at

11°18.3N 120°40.4E

Chart 4706 2Ed 12/2010 [WGS84 Datum] Last NM 10(102)24

Amend light characteristics of Manamoc Island light from Fl(2)W 5s to Fl.10s

at

11°18.3N 120°40.4E

Chart 4707 2Ed 11/2010 [WGS84 Datum] Last NM 10(107)24

Amend light characteristics of Manamoc Island light from Fl(2)W 5s to Fl.10s

at

11°18.3N 120°40.4E

Chart 4723B 2Ed 04/20/2023 [WGS84 Datum] Last NM 10(107)24

Insert



at

11°18.3N 120°40.4E

Chart 5008 1Ed 02/15/2024 [WGS84 Datum] Last NM 11(113)24

Insert



at

11°18.3N 120°40.4E

ENC Affected: PH2CVZ40
(Philippine Coast Guard)

III

TEMPORARY AND PRELIMINARY NOTICES

*11(115)T/24 – BATANES GROUP OF ISLANDS, Batan Island – Light

Mahatao (Shelter) Light, Fl(2)10s, in position 20°25.17'N 121°56.75'E., is unlit and damaged.
(WGS84 DATUM)

Chart Affected: 1506, 1507, 5001, 4280, 4705, 4726A, 2200

ENC Affected: PH3DALUP

(Philippine Coast Guard)

IV LIST OF LIGHTS CORRECTIONS

LIGHTHOUSES

NUMBER (1)	NAME (2)	POSITION (3)	CHARACTERIST ICS (4)	Elev(m) (5)	Range (NM) (6)	STRUCTURE (7)	REMARKS (8)
REGION II - CAGAYAN VALLEY							
BATANES							
	MAHATAO (Shelter)	20 25 10 N 121 56 45 E	Fl(2)10s				TE *
REGION IV-B - MIMAROPA							
PALAWAN							
0331	F2287 MANAMOC ISLAND	11 18 20 N 120 40 21 E	Fl.10s	61	10	Concrete tower, 12	TE 2024 *

Note: Asterisk (*) indicates new information in the column above it

Positions given are approximate and in WGS84 Datum unless otherwise stated in column 8

V
COAST PILOT CORRECTIONS

No Coast Pilot Corrections for this month.

VI

NAVIGATIONAL WARNINGS

See all active Navigational Warnings at <https://staging.geoportal.gov.ph/nwapp/>

NAVPHIL 065/24
MINDORO STRAIT.
AMNAY R, W.

CHART 1552.
DREDGING AND SAND EXTRACTION IN
PROGRESS IN AREA BOUNDED BY:
12-57.20N 120-43.71E
12-57.72N 120-46.15E
12-56.64N 120-46.25E
12-57.03N 120-46.88E
12-56.98N 120-46.96E
12-56.33N 120-46.34E
12-55.23N 120-46.74E
12-54.64N 120-44.35E.

NAVPHIL 204/24
WEST PHILIPPINE SEA.
KALAYAAN ISLAND GROUP.

CHART 4723A.
LIKAS ISLAND LIGHT 11-04.78N 115-01.33E,
F2823.8, UNLIT.

NAVPHIL 227/24
MANILA BAY.

CHART 1501.
OIL SPILL RESPONSE OPERATIONS
ONGOING. TEMPORARY EXCLUSION
ZONE RADIUS FOUR MILES ESTABLISHED
CENTERED ON 14-30.3N 120-40.5E. SHIPS
ARE PROHIBITED FROM ENTERING OR
REMAINING WITHIN THE ZONE. CONTACT
PHILIPPINE COAST GUARD TO ENTER
PROHIBITED AREA AND FOR UPDATED
INFORMATION.

NAVPHIL 266/24
TABLAS STRAIT.

CHART 1543.
SOIL SAMPLING ACTIVITY IN PROGRESS BY
BARGE MCRP 01, 843.00 TONS, AND MTUG
ABIGAIL, 79.00 TONS, UNTIL 31 DEC 2024 IN
AREAS BOUNDED BY:
A. 12-44.64N 121-30.29E
12-44.83N 121-30.71E
12-44.39N 121-31.88E
12-44.25N 121-31.33E
12-44.40N 121-31.10E.
B. 12-51.41N 121-29.61E
12-51.41N 121-30.03E
12-50.62N 121-30.06E
12-50.62N 121-29.70E.
CANCEL THIS MSG 01 JAN 25.

NAVPHIL 272/24
SAMAR SEA.
CALBAYOG CITY.

CHART 1539.
LIGHTBUOYS 12-02.58N 124-35.45E AND 12-
03.35N 124-35.75E UNLIT.

NAVPHIL 274/24
SAN MIGUEL BAY.

CHART 1514.
SCIENTIFIC SURVEY BY MV ST ANTHONY
EXPRESS 4, 35.00 TONS, BARGE LA ROCHE,
463.00 TONS, AND MTUG BELOY, 58.30 TONS,
IN PROGRESS UNTIL 31 DEC IN AREA
BOUNDED BY:
13-52.32N 123-04.15E
13-53.41N 123-17.16E
13-50.34N 123-18.90E
13-48.49N 123-19.43E
13-46.52N 123-17.88E
13-44.42N 123-15.18E
13-43.66N 123-11.18E
13-44.17N 123-07.04E
13-46.42N 123-02.90E
13-49.10N 123-02.96E.
CANCEL NAVPHIL 226/24.
CANCEL THIS MSG ON 01 JAN 25.

NAVPHIL 293/24
BUTUAN BAY.
LA UNION PT, SW.

CHART 1536.
SUBMERGED MOORING BUOY REPORTED
09-04.29N 125-31.05E.

NAVPHIL 299/24.
LUZON SEA AND MANILA BAY.

CHART 1501 AND 1502.
DREDGING AND RECLAMATION ACTIVITIES
BY MV AN DA KANG 689, 5,445.00
TONS, IN PROGRESS UNTIL 30 JUNE 2025 IN
AREAS BOUNDED BY:
A. DREDGING AREA
15-02.55N 120-02.71E
15-02.56N 120-03.35E
15-01.76N 120-03.38E
15-01.76N 120-02.73E,
B. RECLAMATION AREA
14-33.23N 120-57.10E
14-33.28N 120-57.10E
14-33.24N 120-57.66E
14-33.23N 120-57.66E.
CANCEL THIS MSG 01 JULY 25.

VI

NAVIGATIONAL WARNINGS

NAVPHIL 305/24

CALAMIAN GROUP.

CORON PASSAGE.

CHART 1553.

PORT HAND LIGHTBUOY 11-59.30N 120-

14.73E MISSING.

NAVPHIL 307/24

MANILA BAY.

MANILA SOUTH HARBOR.

CHART 4243.

LIGHTBUOY, NNSL 8, 14-34.26N 120-54.64E

OFF STATION TO 14-34.28N

120-54.62E.

NAVPHIL 319/24

PHILIPPINE SEA.

CHART 2200.

CABLE REPAIR BY PETER FABER, 2854

TONS, IN PROGRESS UNTIL 30 NOV

IN THE VICINITY OF THE ALONG LINE

JOINING:

05-29.73N 125 57.67E 05-30.72N 126 01.35E

05-32.81N 126 04.75E 05-40.09N 126 10.58E

05-42.25N 126 14.44E 05-44.94N 126 17.32E

05-45.66N 126 19.89E 05-47.68N 126 23.94E

05-49.37N 126 26.17E 05-51.61N 126 27.92E

05-53.41N 126 30.15E 05-56.82N 126 31.78E

06-00.43N 126 36.71E 06-04.90N 126 43.44E

06-14.78N 126 53.01E 06-26.98N 127 07.70E

06-30.52N 127 19.15E 06-30.54N 127 35.10E

06-35.91N 127 49.68E 06-35.93N 127 59.13E

06-39.23N 128 04.95E 06-45.05N 128 08.40E

07-04.40N 128 38.88E 07-05.64N 128 44.83E

07-08.71N 128 50.08E 07-14.16N 128 53.52E

07-28.37N 129 05.51E 07-32.42N 129 13.29E

07-37.78N 129 22.26E 07-41.82N 129 27.87E

07-55.86N 129 37.74E 08-00.39N 129 44.59E

08-10.86N 129 51.17E 08-12.78N 129 54.06E.

HALF MILE BERTH ADVISED.

CANCEL THIS MSG 01 DEC 24.

NAVPHIL 320/24

ILOILO STRAIT AND GUIMARAS STRAIT.

CHART 1549.

GEOTECHNICAL INVESTIGATION BY MTUG

ANA, 28.30 TONS, AND GALMAEGGI 2,

0.78 TONS, IN PROGRESS UNTIL 31 JAN 25,

ALONG LINES JOINING:

A. 10-46.69N 122-37.16E

10-46.32N 122-38.04E

10-46.25N 122-38.15E

10-46.06N 122-38.31E

10-45.01N 122-39.01E.

B. 10-35.69N 122-42.77E

10-35.34N 122-42.91E

10-35.03N 122-43.12E

10-34.21N 122-43.94E

10-33.81N 122-44.51E

10-33.63N 122-44.95E

10-33.10N 122-47.01E

10-32.96N 122-47.44E

10-32.81N 122-47.75E

10-32.54N 122-48.14E

10-32.09N 122-48.59E.

CANCEL THIS MSG 01 FEB 25.

CANCEL NAVPHIL 110/24 AND 159/24.

NAVPHIL 321/24

BASHI CHANNEL.

CHART 5001.

CABLE LAYING OPERATIONS BY C/S

DEPENDABLE, 12184 TONS, IN PROGRESS

UNTIL FURTHER NOTICE IN AREA BOUNDED

BY:

20-45N 121-00E

22-10N 121-00E

22-10N 122-30E

20-45N 122-30E.

CANCEL NAVPHIL 158/24.

NAVPHIL 335/24

CEBU-MACTAN CHANNEL.

CHART 4447.

HYDROGRAPHIC SURVEY ACTIVITY, 01 NOV

TO 30 DEC, IN AREA BOUNDED BY:

10-19.63N 123-57.86E

10-19.77N 123-58.06E

10-19.60N 123-58.35E

10-19.58N 123-58.18E

10-19.53N 123-58.07E.

CANCEL THIS MSG 01 JAN 25.

NAVPHIL 348/24

MINDANAO SEA AND PHILIPPINE SEA.

CHART 2200.

MARINE OPERATIONS BY CS VEGA, 1,706

TONS, IN PROGRESS UNTIL 31 DEC

IN VICINITY OF LINES JOINING:

A. 05-29.73N 125-57.67E

06-11.21N 126-49.77E

06-39.23N 128-04.95E

07-23.47N 129-01.55E

08-12.78N 129-54.06E.

B. 05-29.73N 125-57.67E

04-57.87N 124-35.02E

04-26.88N 122-33.07E

03-33.54N 120-51.45E.

C. 07-2.31 N 125-32.10E

06-39.46N 125-36.55E

06-07.17N 125-53.51E

05-29.73N 125-57.67E.

WIDE BERTH REQUESTED.

CANCEL THIS MSG 01 JAN 25.

CANCEL NAVPHIL 300/24.

VI

NAVIGATIONAL WARNINGS

NAVPHIL 349/24

DAVAO GULF.

CHART 1523.
MARINE OPERATIONS, BY MV NOTHERN ICE,
140.00TONS, IN PROGRESS UNTIL
30 NOV, IN VICINITY OF LINE JOINING:
6-21.01N 125-45.17E
6-29.73N 125-57.67E.
WIDE BERTH REQUESTED.
CANCEL THIS MSG 01 DEC 24.

NAVPHIL 350/24

LEYTE GULF.

SAN JUANICO STRAIT.
CHART 1539.
SCIENTIFIC OPERATIONS, IN PROGRESS
UNTIL 02 DEC, IN VICINITY:
11-23.51N 124-58.85E
11-23.50N 124-58.96E
11-18.92N 124-58.23E
11-18.90N 124-58.18E
11-18.92N 124-58.18E
11-18.90N 124-58.07E
11-18.89N 124-58.02E
11-18.84N 124-57.88E.
CANCEL THIS MSG 03 DEC 24.

NAVPHIL 351/24.

LUZON SEA.

PINGET I, W.
CHART 1504.
PINGET LIGHT, 17-41.33N 120-21.25E, F2715,
UNLIT.

NAVPHIL 361/24

VERDE ISLAND PASSAGE.

CAPE SANTIAGO.
CHART 1564.
CAPE SANTIAGO LIGHT, 13-46.32N 120-
39.18E, F2614, UNLIT.

NAVPHIL 362/24

PHILIPPINE SEA.

MINDANAO, E.
CHART 2200.
SUBMARINE CABLE REPAIRING WORKS BY
C/S ILE DE BREHAT, IN PROGRESS
UNTIL FURTHER NOTICE, IN VICINITY OF
LINE JOINING:
08-21.00N 130-02.00E
08-33.00N 130-12.00E
08-45.00N 130-25.00E.

NAVPHIL 363/24

PALAWAN, E.

GREEN ISLAND BAY.

CHART 1562.
BARBACAN LIGHT, 10-19.10N 119-21.01E,
F2169.5, UNLIT.

NAVPHIL 381/24

MANILA BAY.

LUZON PT, SW.

CHART 1501.
GUNNERY EXERCISES, IN PROGRESS UNTIL
06 DEC, IN AREA BOUNDED BY:
14-21.00N 120-10.00E
14-21.00N 120-16.00E
14-15.00N 120-16.00E
14-15.00N 120-10.00E.
CANCEL THIS MSG 07 DEC 24.

NAVPHIL 382/24

WEST PHILIPPINE SEA.

PIEDRAS PT, NW.

CHART 1562.
GUNNERY EXERCISES, IN PROGRESS UNTIL
06 DEC, IN AREA BOUNDED BY:
10-18.38N 118-41.63E
10-18.37N 118-44.68E
10-15.35N 118-44.68E
10-15.35N 118-41.63E.
CANCEL THIS MSG 07 DEC 24.

NAVPHIL 383/24

SULU SEA.

MURCIELAGOS IS, NE.

CHART 1534.
SUBMARINE CABLE REPAIR, BY SUBARU,
2,867 TONS, IN PROGRESS UNTIL
21 DEC IN THE VICINITY:
08-09.83N 122-28.21E.
WIDE BERTH REQUESTED.
CANCEL THIS MSG 22 DEC 24.

VII

PUBLICATION NOTICES

1. There is no publication notice for this month.

NAMRIA BULLETIN

1. Mariners are requested to notify the Hydrography Branch, NAMRIA of any changes or discrepancies found on Nautical charts and Nautical publications issued by this office, especially if this affects navigational safety in Philippine Waters. The information may be sent using the Hydrographic Note found on <https://namria.gov.ph/omsis/HNNote10.aspx>.
2. Clients may purchase maps, nautical charts, publications and other maritime products online through <https://namria.gov.ph/eMapa>.
3. Please be advised that effective in October 2023, in alignment with Civil Service Commission Memorandum Circular numbers 22, series of 2014 and 6, series of 2022, and in support of the Department of Energy's energy-efficiency initiatives, we are implementing remote-work practice for non-frontline personnel every Friday. Frontline personnel engaged in critical functions and services will maintain their onsite presence.
4. Frontline personnel can be reached through the following contact numbers: Taguig City, Fort Bonifacio Map Sales Office (MSO) - (02) 8810-4831 to 42 at local 431, (02) 8810-5467, 0956 5587584, and 0915 2777903; San Nicolas, Manila MSO - (02) 8245-9498, (02) 8241-3494 at local 117, 0966 8523814, and 0921 3627524; DENR-Visayas Avenue (MSO) - 0999 6079193 and 0928 4497159; and Client Service Section - css.gismb@namria.gov.ph and 02 88875466.

Nautical Charts, Topographic Maps, Tide and Current Tables, and related publications are available for sale at the NAMRIA Map Sales Offices (MSO). Nautical Charts can also be purchased online thru <https://namria.gov.ph/eMapa/>

Region	Address	MSO STAFF	Phone/Fax
Main	Lawton Avenue, Fort Andres Bonifacio, Taguig City	Michelle Ann M. Aguilar Ana Victoria A. Labor Marlon Y. Aguilar	(02) 8810-4831 to 42 loc 431 (02) 8810-5467 0956 5587584 0915 2777903
NCR	421 Barraca Street, San Nicolas, Binondo, Manila	SN3 Marilou B. Cinco Romeo B. Brizuela Mary Jane M. Montano	(02) 8245-9498 (02) 8241-3494 loc 117 0966 8523814
NCR	FMB Building DENR Compound, Visayas Avenue, Quezon City	Sherry Ann S. Perez Glenn M. De Jesus	0999 6079193 0928 4497159
I	DENR Government Center, Sevilla City, San Fernando, La Union	Ayessa A. Valencia	0905 3443202
II	DENR-Land Evaluation Party Building II, Brgy. Carig, Tuguegarao City	Rubilyn T. Pulpulaan	0917 6519625
III	DENR Compound, Diosdado, Macapagal Gov't. Center. Maipis City, San Fernando, Pampanga	Rosalina M. Libunao	0991 3509756
IVA	Provincial Planning and Development Office, Capitol Complex, Batangas City	Engr. Leda P. Velasquez	0961 4552583
IVB	DENR-PENRO Santa Monica, Puerto Princesa City	Juvy B. Sarmiento Corazon L. Zeñarosa	0916 203 8041
V	DENR-Operation/Survey Division, Rizal Street, Sagpon, Legaspi City, Albay	Isabelita T. Climaco	0906 3363033
VI	Manuel Lagunilla Bldg., DENR Compound, Parola, Iloilo City	Temporarily Closed	
VII	DENR-CENRO Building, Arellano Boulevard corner V. Sotto Street Pier 3, Cebu City	Melchor Togonon Renato B. Alcontin, Jr.	0922 7910372 0931 0010341 0961 4552579
VIII	DENR Compound, Santo Niño Extension, Tacloban City	Temporarily Closed	
IX	Pres. Corazon C. Aquino Regional Government Center, Balintawak, Pagadian City, Zamboanga Del Sur	Ednalyn C. Macahidhid	0955 5826075 0948 2943647
IX	DENR CENRO, West General Vicente Alvarez St., Zone 4, Zamboanga City	Annete P. Flores	0955 8928777
X	DENR Building Macabalan, Cagayan de Oro City, Misamis Oriental	Temporarily Closed	
XI	Kilometer 7, SPED Road, Bangkal, Davao City	Temporarily Closed	
XII	3rd Floor, DENR Building Land Evaluation Survey Section, Aurora Street, Barangay Zone IV Koronadal City, South Cotabato	Jeanyluz B. Bautista	0909 9324745
CARAGA	DENR - Land Management Services Building, Ambago, Butuan City, Agusan del Norte	Maricar E. Siega	0948 3619452