



Republic of the Philippines
Department of Environment and Natural Resources

NATIONAL MAPPING AND RESOURCE INFORMATION AUTHORITY

Date: 19 June 2018

Reference: SBMA Seaport Dept. eMail
(HD 140/18)

Subject : NAVPHIL.INFORMATION

No. of Pages: 1

MESSAGE

NAVPHIL 075/18 – LUZON, W. COAST, SUBIC BAY – MISSING BUOYS

MAIN TRAFFIC LANE CENTER BUOY (#5), AT POSITION 14° 46' 47"N., 120° 12' 48"E., AND MAIN TRAFFIC LANE WEST BUOY (#6), AT POSITION 14° 46' 58"N., 120° 12' 26"E., WERE REPORTED REMOVED FROM THEIR CHARTED POSITIONS AND MAIN TRAFFIC LANE EAST BUOY (#9), AT POSITION 14° 48' 30"N., 120° 15' 34"E., HAS BEEN REPORTED MISSING.

ALL SHIPS/WATERCRAFTS TRANSITING THE VICINITY OF THE ABOVE MENTIONED AREA ARE ADVISED TO TAKE NOTE OF THE INFORMATION AND TAKE NECESSARY PRECAUTIONARY MEASURES.

Commodore JACINTO M CABLAYAN
Director, Hydrography Branch

Please advise by phone/fax if any part of this message is not received



NAMRIA OFFICES:

Main : Lawton Avenue, Fort Bonifacio, 1634 Taguig City, Philippines Tel. No.: (632) 810-4831 to 41

Branch : 421 Barraca St. San Nicolas, 1010 Manila, Philippines, Tel. No. (632) 241-3494 to 98

www.namria.gov.ph

ISO 9001:2008 CERTIFIED FOR MAPPING AND GEOSPACIAL INFORMATION MANAGEMENT