



PHILIPPINE NOTICES TO MARINERS

Monthly Edition No.: 2026-01
31 January 2026

Notices Nos.: 001 to 002

CONTENTS

- I Index of Charts Affected
 - II Chart Corrections
 - III Temporary & Preliminary Notices
 - IV List of Lights Corrections
 - V Coast Pilot Corrections
 - VI Navigational Warnings
 - VII Publication Notices
-

Published by
National Mapping and Resource Information Authority
Lawton Avenue, Fort Bonifacio, Taguig City

ISSN 3028 -1067

Tel: (632) 8241-3494 to 98
Email: csu.hb@namria.gov.ph (NAMRIA Client Service Unit)
Website: www.namria.gov.ph

MARITIME AFFAIRS DIVISION
Maritime Spatial and Safety Information Service
Editorial Board 2026

Editor-In-Chief:

LTJG ANGELICA B PRADO, NAMRIA

Supervising Editor:

ENS ANA LIANE Z ZAUSA, NAMRIA

Verifier:

Hermielyn C. Sagucio

Compilers:

SN3 Anjanette A Crucis, NAMRIA

SN3 Samuel F Soriano, NAMRIA

SN3 Krishna O Lee, NAMRIA

Teresita B. Sarmiento

Jeuzelle Liezel A. Aldave

THE PHILIPPINE NOTICES TO MARINERS is a monthly publication produced by the National Mapping and Resource Information Authority (NAMRIA). It contains the recent chart corrections, updates to nautical publications, and other information that is vital for the safety of navigation on Philippine waters.

Copies in digital format can be obtained by downloading them from the NAMRIA website: <https://namria.gov.ph/downloads.aspx#publications> or by sending a request to ph-msi@namria.gov.ph via email.

Organized chart corrections, cumulative and summary list of chart corrections, as well as online hydrographic notes, are also available through the **Online Maritime Safety Information System (OMSIS)**, <https://isportal.namria.gov.ph/OMSIS/Default.aspx>.

Masters of vessels and other concerned parties are requested to advance any report of dangers to navigation and other information affecting Philippine Charts and Coast Pilots, which may come to their attention, to **The Director, Hydrography Branch**. If such information warrants urgent attention, for instance, the non-existence of aids to navigation, failure of light beacons or similar structures, or discovery of new shoals, all concerned are requested to contact NAMRIA directly through the following portals:


Mail	NAMRIA Hydrography Branch, 421 Barraca St, San Nicolas, 1010 Manila, Philippines
E-mail	ph-msi@namria.gov.ph
Landline	(+632) 8245-0295
Online	https://namria.gov.ph/omsis/HNNote10.aspx .

Active navigational warnings are accessible at <https://staging.geoportal.gov.ph/nwapp/>

EXPLANATORY NOTES

- The Philippine Notices to Mariners is divided into the following sections:

Section I. Index of Charts Affected – Contains the list of all nautical charts that have been affected by Notices to Mariners and the Notice Numbers that have affected them.



Section II. Chart Corrections - Contains corrections to nautical charts in sequential numbers with the indication of the month and year of its issuance. The illustration below describes the elements that comprise a typical notice:

Notice No. preceded by an asterisk “ * ” indicates that the information is based upon the original Philippine source.

Section III. Temporary & Preliminary Notices – Contains Notices to Mariners that temporarily affect the nautical charts or have preliminary information that is subject to further verification. The capital “P” or “T” affixed in the number of any notice denotes “*preliminary*” or “*temporary*”, respectively.

A list of Temporary and Preliminary Notices that are still in force is published in this publication every month. The list may be read on Page v.

Section IV. List of Lights Corrections – Contains the corrections to the latest edition of the Philippine List of Lights. The entire entry for each light will be printed and the columns that contain updates will be denoted by an asterisk “ * ”. All columns will be denoted by asterisks in the case of new lights.

This section is intended to be printed, cut out, and pasted on the section of the List of Lights that is being corrected.

All updates to lighted aids, including their operational status, will be published in this section. All directions and bearings are measured clockwise from True North 000° to 360°. Bearing on lights is based on the observer from seaward toward the light. The visibility assigned to the lights never exceeds the calculated distance at which they can be seen from a height of 4.57 meters above the level of the water at high tide.

Changes in aids to navigation, their maintenance, and the correction of deficiencies in operation are under the operation of the Philippine Coast Guard. Report of defects and recommendations concerning aids to navigation should also be forwarded to the Commandant of the Philippine Coast Guard.

Section V. Coast Pilot Corrections – Contains the corrections to the latest editions of the Philippine Coast Pilot books.

Section VI. Navigational Warnings – Contains the reprints of all previously issued navigational warnings that are still in effect as of the publication date of this edition of the Philippine Notices to Mariners.

Section VII. Publication Notices – Contains the latest updates on the nautical charts, electronic navigational charts, and other nautical publications of NAMRIA.

2. NAMRIA issues Notices to Mariners and Navigational Warnings sourced from private entities, foreign publications, national government agencies, and local government units. Such information is published for the sake of the safety of navigation on Philippine waters and does not imply recognition of the legal validity of the information issued by the abovementioned sources.
3. While every effort is made to ensure the accuracy of NAMRIA nautical charts and publications, users should bear in mind that they may not be complete or up-to-date, especially in areas where there are extensive developments. Mariners are advised to exercise prudence and to also refer to all navigational equipment aboard the ship and use a lookout during navigation.
4. Masters of vessels are warned that great care should be exercised in navigating Philippine waters because of the low visibility and occasional failure of some navigational lights. Buoys and beacons are sometimes lost or destroyed, especially after typhoons. Temporary deficiencies in the standard aids to navigation published in this office may have been corrected before subsequent notice is issued.
5. Positions obtained from satellite navigation systems, such as GPS, are normally referred to the WGS-84 Datum. Such position may only be plotted on NAMRIA nautical charts that are also referred to the WGS-84 Datum. Mariners should take note that, due to the age and quality of some of the information, such satellite-derived positions may be more accurate than charted details.

List of Temporary and Preliminary Notices

(in force as of 31 January 2026)

07(029)T/25 LUZON, W. Coast, Pasig River – Light
07(028)T/25 PALAWAN, E. Coast. Sir John Brooke Point – Light
07(027)T/25 CEBU, E. COAST, Cebu Harbor – Wreck
06(024)T/25 WEST PHILIPPINE SEA, Kalayaan Island Group, Patag I – Light
04(011)P/25 Cebu, E. Coast, Cebu Harbor - Traffic separation scheme. Precautionary area.
03(009)T/25 LUZON, S. Coast, Alabat Island - Light
01(003)P/25 Cebu, E. Coast, Cebu Harbor - Dredged Area
01(002)T/25 LUZON, N. Coast, Port San Vicente – Light
01(001)T/25 DAVAO, NE. Coast, Pakiputan Strait – Buoys
11(115)T/24 BATANES GROUP OF ISLANDS, Batan Island – Light
10(110)T/24 LUZON, W. Coast, Manila Bay – Wreck. Restricted Area
10(109)T/24 LUZON, W. Coast, Manila Bay – Buoy
09(101)P/24 LUZON, W. Coast, Zambales – Dredging
09(100)P/24 LUZON, W. Coast, Manila Bay – Reclamation
08(092)T/24 WEST PHILIPPINE SEA, Julian Felipe Reef – Buoys
08(091)T/24 LUZON, S. Coast, Odiongan Bay – Buoy
08(090)T/24 LEYTE, S. Coast, San Juan – Lights
08(089)T/24 LEYTE, N. Coast, Biliran I – Light
08(088)T/24 SAMAR, W. Coast – Lights
08(087)T/24 SAMAR, NE. Coast, Hiuinatungan I – Light
08(086)T/24 KALAYAAN ISLAND GROUP, Pag-asa Island – Buoy
07(073)T/24 LUZON, S. COAST, Sibuyan I – Lights
07(072)T/24 LUZON, NE. COAST – Lights
07(071)T/24 PHILIPPINE RISE, Benham Bank – Buoys
07(070)T/24 PALAWAN, N. COAST, Coron Passage – Buoys
07(069)T/24 LUZON, S. COAST, Sibuyan Island – Lights
07(068)T/24 LUZON, S. COAST, Laguna de Bay – Lights
07(067)T/24 LUZON, N. COAST, Batan Island – Light
07(066)T/24 LUZON, W. COAST, Manila Bay – Anchorage
07(065)T/24 LUZON, NE. COAST, Padsan River – Dredging
09(114)P/23 LUZON. S. COAST, Batangas Bay – Terminal
03(048)T/23 PALAWAN, E. COAST, off Miniloc Island – Buoy
03(047)T/23 BOHOL, W. COAST, Dawahon Bank – Light
02(032)T/23 PALAWAN, N. COAST, Coron Bay – Buoy
02(031)T/23 LUZON, W. COAST, Manila Bay – Buoy
01(020)T/23 LUZON, W. COAST, Manila Bay - Buoy
12(077)T/22 MASBATE, NORTH COAST, Masbate Harbor – Beacon
09(040)T/22 LUZON, W. COAST, Manila Bay – Buoy
07(032)T/22 LUZON, W. COAST, Manila Bay – Buoy
07(031)T/22 LUZON, W. COAST, Manila Bay – Buoy
05(022)T/22 LUZON, W. COAST, Manila Bay – Buoy
02(014)P/17 MINDANAO, N. COAST, Butuan Bay – Submarine Pipeline

TABLE OF CONTENTS

Index of Charts Affected - - - - -	01
Chart Corrections - - - - -	02
Temporary & Preliminary Notices - - - - -	03
List of Lights Corrections - - - - -	04
Coast Pilot Corrections - - - - -	05
Navigational Warnings - - - - -	06
Publication Notices - - - - -	09

I
INDEX OF CHARTS AFFECTED

Chart No	Notice No.	Chart No	Notice No.
1511	01(002)26	PH2CVZ40	01(001)26
1512	01(002)26	PH2NLZ40	01(002)26
4227	01(002)26		
4726A	01(002)26		
4705	01(002)26		
1542	01(001)26		
4706	01(001)26		
4715	01(001)26		

II

CHART CORRECTIONS

01(001)26 – LUZON, S. COAST, Ragay Gulf – Light

Chart 1542 2Ed 30/06/2024 [WGS-84 DATUM] Last NM 07(057)24

Amend characteristics of Laganac Light from Fl(3)5s to Fl.10s

at 13°20.53'N 123°12.78'E

Chart 4706 2Ed 12/2010 [WGS-84 DATUM] Last NM 11(044)25

Amend characteristics of Laganac Light from Fl(3)5s to Fl.10s

at 13°20.5'N 123°12.8'E

Chart 4715 1Ed 12/1958 [LUZON DATUM] Last NM 11(044)25

Amend characteristics of Laganac Light from Fl(3)5s to Fl.10s

at 13°20.6'N 123°12.7'E

ENCs Affected: PH2CVZ40

Philippine Coast Guard

01(002)26 – LUZON, E. COAST, Dikapinisan Point - Geographic Name

Chart 1511 1Ed 04/12/2022 [WGS-84 DATUM]

Amend geographic name Dicapinisan Point to Dikapinisan Point

at 15°32.76'N 121°31.84'E

Chart 1512 1Ed 04/27/2022 Last NM 08(094)23

Amend geographic name Dicapinisan Point to Dikapinisan Point

at 15°32.76'N 121°31.84'E

Chart 4227 1Ed 24/ 09/1962; Revised 01/86 Last NM 02(029)23

Amend geographic name Dicapinisan Point to Dikapinisan Point

at 15°32.61'N 121°31.91'E

Chart 4726A 5th Ed 02/26/2025 Last NM 11(043)25

Amend geographic name Dicapinisan Point to Dikapinisan Point

at 15°32.61'N 121°31.91'E

Chart 4705 3rd Ed 03/2010; Corrected to NM 10/2012 Last NM 06(022)25

Amend geographic name Dicapinisan Point to Dikapinisan Point

at 15°32.61'N 121°31.91'E

ENCs Affected: PH2NLZ40

National Mapping and Resource Information Authority

III

TEMPORARY AND PRELIMINARY NOTICES

There is no temporary and preliminary notice for this month.

IV

LIST OF LIGHTS CORRECTIONS

LIGHTHOUSES

NUMBER (1)	NAME (2)	POSITION (3)	CHARACTERISTICS (4)	Elev(m) (5)	Range (NM) (6)	STRUCTURE (7)	REMARKS (8)
REGION V – BICOL REGION							
CAMARINES SUR							
0549	F2504	LAGANAC	13 20 36 N 123 12 42 E *	Fl.10s		GRP	Luzon Datum

Note: Asterisk (*) indicates new information in the column above it. Positions given are approximate and in WGS84 Datum unless otherwise stated in column 8.

V

COAST PILOT CORRECTIONS

Philippine Coast Pilot, 8th Ed. Volume IA

Chapter 5 – LUZON ISLAND

page 5-85, right column, line 54-55

Replace: DICAPANISAN POINT, located about 7 miles SW
of Dibayabay Bay, is marked by Dikapinisan Light (15°

VI

NAVIGATIONAL WARNINGS

See all active Navigational Warnings at
<https://staging.geoportal.gov.ph/nwapp/>

NAVPHIL 272/24
SAMAR SEA.
CALBAYOG CITY.
CHART 1539.
LIGHTBUOYS 12-02.58N 124-35.45E AND 12-03.35N 124-35.75E UNLIT.

NAVPHIL 293/24
BUTUAN BAY.
LA UNION PT, SW.
CHART 1536.
SUBMERGED MOORING BUOY REPORTED
09-04.29N 125-31.05E.

NAVPHIL 307/24
MANILA BAY.
MANILA SOUTH HARBOR.
CHART 4243.
LIGHTBUOY, NNSL 8, 14-34.26N 120-54.64E
OFF STATION TO 14-34.28N
120-54.62E.

NAVPHIL 351/24.
LUZON SEA.
PINGET I, W.
CHART 1504.
PINGET LIGHT, 17-41.33N 120-21.25E, F2715,
UNLIT.

NAVPHIL 361/24
VERDE ISLAND PASSAGE.
CAPE SANTIAGO.
CHART 1564.
CAPE SANTIAGO LIGHT, 13-46.32N 120-39.18E, F2614, UNLIT.

NAVPHIL 362/24
PHILIPPINE SEA.
MINDANAO, E.
CHART 2200.
SUBMARINE CABLE REPAIRING WORKS BY
C/S ILE DE BREHAT, IN PROGRESS
UNTIL FURTHER NOTICE, IN VICINITY OF
LINE JOINING:
08-21.00N 130-02.00E
08-33.00N 130-12.00E
08-45.00N 130-25.00E.

NAVPHIL 386/24
MACAJALAR BAY.
MACABALAN PORT.
CHART 4646.
MACABALAN LIGHT, 08-30.42N 124-39.70E,
F2266, UNLIT.

NAVPHIL 065/25
LAMON BAY.
PORT ALABAT.
CHART 1513.
ALABAT PORT LIGHT 14-05.93N 122-055E
TEMPORARILY REMOVED.

NAVPHIL 105/25
MANILA BAY.
LIMAY PT, E.
CHART 4250.
1. WRECK REMOVAL OPERATIONS IN
PROGRESS 14-30.32N 120-40.46E. A
TEMPORARY EXCLUSION ZONE RADIUS
THREE NAUTICAL MILES HAS BEEN
ESTABLISHED CENTERED ON THIS
POSITION.
2. SHIPS ARE PROHIBITED FROM ENTERING
OR REMAINING WITHIN THIS ZONE.

NAVPHIL 159/25
MANILA BAY.
PASAY.
CHART 1501.
DREDGING OPERATIONS IN PROGRESS BY
JIN XIN 709 IN AREA BOUND BY
14-33.54N, 120-58.64E, 14-31.62N, 120-58.75E,
14-31.63N, 120-57.58E, 14-31.69N, 120-57.14E,
14-32.07N, 120-57.14E, 14-33.01N, 120-57.24E,
14-33.42N, 120-58.17E.

NAVPHIL 160/25
LUZON SEA
CHART 1501.
DREDGING OPERATIONS IN PROGRESS BY
MV SANKO UNO 68 AND DREDGE MASTER 5
IN AREAS BOUND BY:
A.
14-25.88N 120-23.98E, 14-27.04N 120-24.63E,
14-26.35N 120-25.39E, 14-26.26N 120-27.21E,
14-24.86N 120-26.59E, 14-25.39N 120-24.94E.
B.
14-27.42N 120-22.09E, 14-28.36N 120-21.71E,
14-29.93N 120-21.44E, 14-30.05N 120-22.57E,
14-28.41N 120-22.85E, 14-28.02N 120-23.07E.

NAVPHIL 174/25
LUZON SEA.
SANTO TOMAS R, W.
CHART 1502.
DREDGING OPERATIONS IN PROGRESS BY
MV HONG FA 569 IN AREA BOUND BY
15-02.55N 120-02.71E, 15-02.58N 120-03.16E,
15-01.76N 120-03.38E, 15-01.75N 120-02.73E.

NAVPHIL 175/25
MANILA BAY.
PASAY CITY.
CHART 1501.

VI

NAVIGATIONAL WARNINGS

DREDGING OPERATIONS IN PROGRESS BY
MV HONG FA 569 IN AREA BOUND BY
14-33.23N 120-57.10E, 14-33.28N 120-57.10E,
14-33.28N 120-57.66E, 14-33.24N 120-57.66E.

NAVPHIL 183/25
LUZON SEA.
ABRA R.

CHART 1504.
DREDGING OPERATIONS IN PROGRESS BY
MV YONG XIN 1 IN AREAS BOUND BY:
A. 17-30.77N 120-24.98E, 17-30.19N 120-
23.33E,
17-30.49N 120-23.19E, 17-33.61N 120-27.18E.
B. 17-30.47N 120-23.03E, 17-29.17N 120-
23.84E,
17-29.17N 120-24.72E, 17-28.20N 120-24.72E,
17-28.19N 120-23.85E, 17-28.74N 120-23.10E,
17-28.66N 120-22.97E, 17-29.96N 120-22.16E.

NAVPHIL 211/25
SAN MIGUEL BAY.
SIRUMA I, NW.

CHART 1514.
DANGEROUS WRECK REPORTED IN
14-02.20N 123-11.49E.

NAVPHIL 254/25
LUZON SEA.
SANTO TOMAS R, W.

CHART 1502.
1. DREDGING OPERATIONS IN PROGRESS
UNTIL 22 SEP 2026 BY MV SANKO UNO 13 IN
AREA BOUND BY
15-02.55N 120-02.71E, 15-02.56N 120-03.35E,
15-01.76N 120-03.37E, 15-01.75N 120-02.73E.
2. CANCEL THIS MSG 23 SEP 2026.

NAVPHIL 255/25
MANILA BAY.

CHART 1501.
1. DREDGING OPERATIONS IN PROGRESS
UNTIL 22 SEP 2026 BY MV SANKO UNO 13 IN
AREA BOUND BY
14-33.22N 120-57.10E, 14-33.27N 120-57.10E,
14-33.27N 120-57.65E, 14-33.23N 120-57.65E.
2. CANCEL THIS MSG 23 SEP 2026.

NAVPHIL 264/25
PHILIPPINE SEA.
LUZON I, EAST COAST.

CHART 4705.
HYDROGRAPHIC SURVEY IN PROGRESS BY
ANGGE ALONG LINE JOINING
15-46.70N 121-33.58E, 15-46.90N 121-38.06E,
15-46.69N 121-39.73E, 15-45.82N 121-42.24E,
15-40.18N 121-47.67E, 15-39.42N 121-49.91E,
15-40.80N 121-52.72E, 15-44.03N 121-57.14E,
15-55.73N 122-08.49E, 16-09.21N 122-20.94E,

16-28.84N 122-34.15E, 16-37.81N 122-38.89E,
16-50.57N 122-45.65E, 17-34.66N 122-47.85E,
18-00.56N 122-53.86E, 18-13.92N 123-05.27E,
18-19.47N 123-07.52E, 18-29.68N 123-06.77E,
18-38.08N 123-05.18E, 18-48.69N 123-03.17E,
18-56.62N 123-01.66E, 19-00.67N 123-00.94E.
WIDE BERTH REQUESTED.

NAVPHIL 279/25
PAKIPUTAN STRAIT.
SAMAL I. W.

CHART 1523.
1. CABLE LAYING OPERATIONS IN
PROGRESS BY LCT BLUE DRAGON UNTIL 30
JAN 2026 IN VICINITY OF LINE JOINING
07-06.86N 125-39.48E, 07-06.70N 125-39.66E,
07-06.53N 125-39.86E.
2. CANCEL THIS MSG 01 FEB 2026

NAVPHIL 282/25
PHILIPPINE SEA.
BALER BAY TO BALINTANG CHANNEL

CHART 4726A.
1. HYDROGRAPHIC SURVEY IN PROGRESS
UNTIL 30 JAN 2026 BY MBCA
JHAZIENE RHAJ ALONG A LINE JOINING
15 46.70N 121 33.58E, 15 46.90N 121 38.06E,
15 46.69N 121 39.73E, 15 45.82N 121 42.24E,
15 40.18N 121 47.67E, 15 39.41N 121 49.91E,
15 40.80N 121 52.72E, 15 44.03N 121 57.14E,
15 55.73N 122 08.49E, 16 09.21N 122 20.94E,
16 28.84N 122 34.15E, 16 37.81N 122 38.89E,
16 50.57N 122 45.65E, 17 34.66N 122 47.85E,
18 00.56N 122 53.86E, 18 13.92N 123 05.27E,
18 19.47N 123 07.52E, 18 29.68N 123 06.77E,
19 23.50N 122 57.17E, 19 39.54N 122 59.37E,
19 51.75N 123 06.14E.
WIDE BERTH REQUESTED.
2. CANCEL THIS MSG 31 JAN 2026.

NAVPHIL 289/25
MANILA BAY.
MANILA HARBOR, N.

CHART 4236.
1. DREDGING OPERATIONS IN PROGRESS
UNTIL 01 FEB 2026 BY BARGE FCC BD-539
and MTUG JOSIE II IN AREA BOUND BY
14-38.06N 120-57.04E, 14-38.08N 120-57.05E,
14-38.08N 120-56.95E, 14-38.11N 120-57.15E,
14-38.10N 120-57.15E, 14-38.06N 120-57.14E.
2. CANCEL THIS MSG 02 FEB 2026.

NAVPHIL 001/26
MANILA BAY.

CHART 1501.
1. HYDROGRAPHIC SURVEY IN PROGRESS
UNTIL 31 JAN 2026 BY MB 510 FISHABOUT IN
AREA BOUND BY
14-31.78N 120-58.69E, 14-31.80N 120-58.80E,

VI

NAVIGATIONAL WARNINGS

14-31.78N 120-58.80E, 14-31.77N 120-58.75E,
14-31.45N 120-58.76E, 14-31.45N 120-58.71E.
WIDE BERTH REQUESTED.
2. CANCEL THIS MSG 01 FEB 2026.

NAVPHIL 002/26
MANGARIN BAY
CAMINAWIT PT. S.
CHART 1552.

1. DREDGING OPERATIONS IN PROGRESS
UNTIL 25 MAR 2026 BY BARGE JOVINA AND
MTUG VITARA IN AREA BOUND BY:
12-19.65N 121-5.15E, 12-19.65N 121-5.18E,
12-19.63N 121-5.18E, 12-19.63N 121-5.12E,
12-19.65N 121-5.10E, 12-19.65N 121-5.07E,
12-19.67N 121-5.03E, 12-19.68N 121-5.05E,
12-19.67N 121-5.07E, 12-19.67N 121-5.13E.
2. CANCEL THIS MSG 26 MAR 2026.

NAVPHIL 006/26
MANILA BAY.
CHART 1501.

1. DREDGING OPERATIONS IN PROGRESS
UNTIL 30 JUN 2026 BY VARIOUS
VESSELS IN AREA BOUND BY
14-44.06N, 120-50.52-E,
14-43.90N, 120-50.73-E,
14-43.89N, 120-50.62-E,
14-41.88N, 120-49.01-E,
14-41.95N, 120-48.92-E,
14-43.96N, 120-50.53-E.
2. CANCEL THIS MSG 01 JUL 2026.

NAVPHIL 007/26

CUYO EAST PASS.
PANAY I, W.
CHART 2200.

1. HYDROGRAPHIC SURVEY IN PROGRESS
UNTIL 16 MAR 2026 BY USNS
BOWDITCH IN AREA BOUND BY
11-45.08N, 121-51.27E,
09-04.59N, 121-51.09E,
09-00.79N, 121-23.46E,
11-29.05N, 121-11.74E.
WIDE BERTH REQUESTED.
2. CANCEL THIS MSG 17 MAR 2026.

NAVPHIL 008/26
WEST PHILIPPINE SEA.
MALAMPAYA GAS FIELD.
CHART 4723B.

1. SCIENTIFIC OPERATIONS IN PROGRESS
UNTIL 15 FEB 2026 BY PACIFIC
GUILLEMOT AND DEMAREST TIDE IN
VICINITY AREAS:
A. 11-38.23N 118-56.36E
B. 11-34.10N 118-53.54E
C. 11-48.76N 118-57.68E

WIDE BERTH REQUESTED.
2. CANCEL THIS MSG 16 FEB 2026.

NAVPHIL 011/26
MANILA BAY.
PANDAN PT, E.
CHART 1501.

1. NAVAL FIRING EXERCISES IN PROGRESS
UNTIL 31 JAN 2026 IN AREA BOUND BY:
14-43.40N, 120-34.20E,
14-45.38N, 120-42.85E,
14-36.09N, 120-45.82E,
14-34.03N, 120-37.01E.
2. CANCEL THIS MSG 01 FEB 2026.

NAVPHIL 012/26
LUZON, N.
BABUYAN CHANNEL.
CHART 5001.

1. CABLE LAYING OPERATIONS IN
PROGRESS UNTIL 12 FEB 2026 BY CS
NORMAND CLIPPER ALONG A LINE JOINING
18-39.88N 121-18.95E,
18-43.95N 122-23.12E.
WIDE BERTH REQUESTED.
2. CANCEL THIS MSG 13 FEB 2026.

NAVPHIL 013/26
MANILA BAY.
CORREGIDOR I.
CHART 1501.

VTMS RADAR STATION 2, 14-22.87N 120-
34.61E, INOPERATIVE.

NAVPHIL 014/26
LUZON SEA.
LOS FRAILES, SW.
CHART 1501.

1. NAVAL FIRING EXERCISES IN PROGRESS
UNTIL 31 JAN 2026 IN AREA
BOUND BY
14-34.87N 119-40.07E,
14-34.76N 119-50.06E,
14-24.85N 119-50.34E,
14-24.87N 119-40.03E.
2. CANCEL THIS MSG 01 FEB 2026.

NAVPHIL 015/26
CUYO I, W.
CHART 1551.
Q, 10-50.82N 120-29.63E, UNLIT.

VII

PUBLICATION NOTICES

1. Newly published and updated Nautical Chart.
 - a. Chart 1530 – Pangutaran Group to Tapul Group Including Jolo Group
Scale 1:150 000, 2nd Edition, 11 December 2025

NAMRIA BULLETIN

1. Mariners are requested to notify the Hydrography Branch, NAMRIA of any changes or discrepancies found on Nautical charts and Nautical publications issued by this office, especially if this affects navigational safety in Philippine Waters. The information may be sent using the Hydrographic Note found at <https://namria.gov.ph/omsis/HNNote10.aspx>.
2. Clients may purchase maps, nautical charts, publications, and other maritime products online at <https://namria.gov.ph/eMapa>.
3. Please be advised that effective in October 2023, in alignment with Civil Service Commission Memorandum Circular numbers 22, series of 2014 and 6, series of 2022, and in support of the Department of Energy's energy-efficiency initiatives, we are implementing remote-work practice for non-frontline personnel every Friday. Frontline personnel engaged in critical functions and services will maintain their onsite presence.
4. Frontline personnel can be reached through the following contact numbers: Taguig City, Fort Bonifacio Map Sales Office (MSO) - (02) 8810-4831 to 42 at local 431, (02) 8810-5467, 0956 5587584, and 0915 2777903; San Nicolas, Manila MSO - (02) 8245-9498, (02) 8241-3494 at local 117, 0966 8523814, and 0921 3627524; DENR-Visayas Avenue (MSO) - 0999 6079193 and 0928 4497159; and Client Service Section - css.gismb@namria.gov.ph and 02 88875466.

Nautical Charts, Topographic Maps, Tide and Current Tables, and related publications are available for sale at the NAMRIA Map Sales Offices (MSO). Nautical Charts can also be purchased online thru <https://namria.gov.ph/eMapa/>

Region	Address	MSO STAFF	Phone/Fax
(Main) Taguig City	Lawton Avenue, Fort Andres Bonifacio, Taguig City	Michelle Ann M. Aguilar Ana Victoria A. Labor Marlon Y. Aguilar	(02) 8810-4831 to 42 loc 431 (02) 8810-5467 0956 5587584 0915 2777903
Manila	421 Barraca Street, San Nicolas, Binondo, Manila	SN3 Marilou B. Cinco Romeo B. Brizuela Mary Jane M. Montano	(02) 8245-9498 (02) 8241-3495 loc 117 0966 8523814
Quezon City	Forest Management Bureau (FMB) Building, Visayas Avenue, Quezon City	Sherry Ann S. Perez Glenn M. De Jesus	0999 6079193 0928 4497159
I	DENR Government Center, Sevilla, San Fernando, La Union	Ayessa A. Valencia	0905 3443202
II	DENR-Land Evaluation Party (LEP), Building II, Carig, Tuguegarao City	Rubilyn T. Pulpulaan	0917 6519625
III	DENR Compound, Diosdado Macapagal Gov't. Center, Maimpis, City of San Fernando, Pampanga	Rosalina M. Libunao	0991 3509756
IVA	Provincial Planning and Development Office, Laurel Park, Capitol Complex, Batangas City	Engr. Leda P. Velasquez	0961 4552583
IVB	DENR-PENRO - Santa Monica, Puerto Princesa City, Palawan	Juvy B. Sarmiento Corazon L. Zeñarosa	0916 203 8041
V	DENR-Operation/Survey Division, Rizal Street, Sagpon, Legaspi City, Albay	Isabelita T. Climaco	0906 3363033
VI	Manuel Lagunilla Bldg., DENR Compound, Parola, Iloilo City		0935-3632796
VII	DENR-CENRO Building, Arellano Boulevard corner V. Sotto Street Pier 3, Cebu City	Melchor Togonon Renato B. Alcontin, Jr.	0922 7910372 0931 0010341 0961 4552579
IX	Pres. Corazon C. Aquino Regional Government Center, Balintawak, Pagadian City, Zamboanga Del Sur	Ednalyn C. Macahidhid	0955 5826075 0948 2943647
IX	DENR CENRO, West General Vicente Alvarez St., Zone 4, Zamboanga City	Annete P. Flores	0955 8928777
X	DENR Building Macabalan, Cagayan de Oro City, Misamis Oriental		0935-5630463
XI	Kilometer 7, SPED Road, Bangkal, Davao City	Temporarily Closed	N/A
XII	3rd Floor, DENR Building Land Evaluation Survey Section, Aurora Street, Barangay Zone IV Koronadal City, South Cotabato	Jeanyluz B. Bautista	0909 9324745
CARAGA	DENR - Land Management Services Building, Ambago, Butuan City, Agusan del Norte	Maricar E. Siega	0948 3619452