



PHILIPPINE NOTICES TO MARINERS

Monthly Edition No.: 2025-07
31 July 2025

Notices Nos.: 026 to 029

CONTENTS

- | | |
|-----|---------------------------------|
| I | Index of Charts Affected |
| II | Chart Corrections |
| III | Temporary & Preliminary Notices |
| IV | List of Lights Corrections |
| V | Coast Pilot Corrections |
| VI | Navigational Warnings |
| VII | Publication Notices |
-

Published by
National Mapping and Resource Information Authority
Lawton Avenue, Fort Bonifacio, Taguig City

ISSN 3028 -1067

Tel: (632) 8241-3494 to 98
Email: csu.hb@namria.gov.ph (NAMRIA Client Service Unit)
Website: www.namria.gov.ph

MARITIME AFFAIRS DIVISION
Maritime Spatial and Safety Information Service
Editorial Board 2025

Editor-In-Chief:
LCDR MAY ANNE L JAVIER, NAMRIA

Supervising Editor:
P/ENS ANA LIANE Z ZAUSA, NAMRIA

Verifier:
Hermielyn C. Sagucio

Compilers:
SN3 Anjanette A Crucis, NAMRIA
SN3 Rhean Mark A Monilla, NAMRIA
SN3 Samuel F Soriano, NAMRIA
SN3 Krishna O Lee, NAMRIA
Teresita B. Sarmiento

THE PHILIPPINE NOTICES TO MARINERS is a monthly publication produced by the National Mapping and Resource Information Authority (NAMRIA). It contains the recent chart corrections, updates to nautical publications, and other information that is vital for the safety of navigation on Philippine waters.

Copies in digital format may be obtained or by downloading at the NAMRIA website: <https://namria.gov.ph/downloads.aspx#publications> or by sending a request through the email address ph-msi@namria.gov.ph.

Organized chart corrections, cumulative and summary list of chart corrections as well as online hydrographic notes are also available through the **Online Maritime Safety Information System (OMSIS)**, <https://isportal.namria.gov.ph/OMSIS/Default.aspx>.

Masters of vessels and other concerned parties are requested to advance any report of dangers to navigation and other information affecting Philippine Charts and Coast Pilots, which may come to their attention, to the **Director, Hydrography Branch**. If such information warrants urgent attention, for instance, the non-existence of aids to navigation, failure of light beacons or similar structures, or discovery of new shoals, all concerned are requested to contact NAMRIA directly through the following portals:


Mail	NAMRIA Hydrography Branch, 421 Barraca St San Nicolas, 1010 Manila, Philippines
E-mail	ph-msi@namria.gov.ph
Landline	(+632) 8245-0295
Online	https://namria.gov.ph/omsis/HNNote10.aspx .

Active navigational warnings are accessible at <https://staging.geoportal.gov.ph/nwapp/>

EXPLANATORY NOTES

1. The Philippine Notices to Mariners is divided into the following sections:

Section I. Index of Charts Affected – Contains the list of all nautical charts that have been affected by Notices to Mariners and the Notice Numbers that have affected them.



Section II. Chart Corrections - Contains corrections to nautical charts in sequential numbers with the indication of the month and year of its issuance. The illustration below describes the elements that comprise a typical notice:

Notice No. preceded by an asterisk “*” indicates that the information is based upon the original Philippine source.

Section III. Temporary & Preliminary Notices – Contains Notices to Mariners that temporarily affect the nautical charts or have preliminary information that is subject to further verification. The capital “P” or “T” affixed in the number of any notice denotes “*preliminary*” or “*temporary*”, respectively.

A list of Temporary and Preliminary Notices that are still in force is published in this publication every month. The list may be read on Page v.

Section IV. List of Lights Corrections – Contains the corrections to the latest edition of the Philippine List of Lights. The entire entry for each light will be printed and the columns that contain updates will be denoted by an asterisk “*”. All columns will be denoted by asterisks in the case of new lights.

This section is intended to be printed, cut out, and pasted on the section of the List of Lights that is being corrected.

All updates to lighted aids, including their operational status, will be published in this section. All directions and bearings are measured clockwise from True North 000° to 360°. Bearing on lights is based on the observer from seaward toward the light. The visibility assigned to the lights never exceeds the calculated distance at which they can be seen from a height of 4.57 meters above the level of the water at high tide.

Changes in aids to navigation, their maintenance, and correction of deficiencies in operation are under the operation of the Philippine Coast Guard. Report of defects and recommendations concerning aids to navigation should also be forwarded to the Commandant of the Philippine Coast Guard.

Section V. Coast Pilot Corrections – Contains the corrections to the latest editions of the Philippine Coast Pilot books.

Section VI. Navigational Warnings – Contains the reprints of all previously issued navigational warnings that are still in effect as of the publication date of this edition of the Philippine Notices to Mariners.

Section VII. Publication Notices – Contains the latest updates on the nautical charts, electronic navigational charts, and other nautical publications of NAMRIA.

2. NAMRIA issues Notices to Mariners and Navigational Warnings sourced from private entities, foreign publications, national government agencies, and local government units. Such information is published for the sake of the safety of navigation on Philippine waters and does not imply recognition of the legal validity of the information issued by the abovementioned sources.
3. While every effort is made to ensure the accuracy of NAMRIA nautical charts and publications, users should bear in mind that it may not be complete or up-to-date, especially in areas where there are extensive developments. Mariners are advised to exercise prudence and to also refer to all navigational equipment aboard the ship and use a lookout during navigation.
4. Masters of vessels are warned that great care should be exercised in navigating Philippine waters because of the low visibility and occasional failure of some navigational lights. Buoys and beacons are sometimes lost or destroyed, especially after typhoons. Temporary deficiencies in the standard aids to navigation published in this office may have been corrected before subsequent notice is issued.
5. Positions obtained from satellite navigation systems, such as GPS, are normally referred to the WGS-84 Datum. Such position may only be plotted on NAMRIA nautical charts that are also referred to the WGS-84 Datum. Mariners should take note that due to the age and quality of some of the information, such satellite-derived positions may be more accurate than charted details.

List of Temporary and Preliminary Notices

(in force as of 31 July 2025)

07(029)T/25 LUZON, W. Coast, Pasig River – Light
07(028)T/25 PALAWAN, E. Coast. Sir John Brooke Point – Light
07(027)T/25 CEBU, E. COAST, Cebu Harbor – Wreck
06(025)T/25 MINDANAO, N. Coast, Iligan Bay – Light
06(024)T/25 WEST PHILIPPINE SEA, Kalayaan Island Group, Patag I – Light
04(011)P/25 Cebu, E. Coast, Cebu Harbor - Traffic separation scheme. Precautionary area.
03(009)T/25 LUZON, S. Coast, Alabat Island - Light
01(003)P/25 Cebu, E. Coast, Cebu Harbor - Dredged Area
01(002)T/25 LUZON, N. Coast, Port San Vicente – Light
01(001)T/25 DAVAO, NE. Coast, Pakiputan Strait – Buoys
11(115)T/24 BATANES GROUP OF ISLANDS, Batan Island – Light
10(110)T/24 LUZON, W. Coast, Manila Bay – Wreck. Restricted Area
10(109)T/24 LUZON, W. Coast, Manila Bay – Buoy
10(108)T/24 DAVAO, NE. Coast, Pakiputan Strait – Buoys
09(101)P/24 LUZON, W. Coast, Zambales – Dredging
09(100)P/24 LUZON, W. Coast, Manila Bay – Reclamation
08(092)T/24 WEST PHILIPPINE SEA, Julian Felipe Reef – Buoys
08(091)T/24 LUZON, S. Coast, Odiongan Bay – Buoy
08(090)T/24 LEYTE, S. Coast, San Juan – Lights
08(089)T/24 LEYTE, N. Coast, Biliran I – Light
08(088)T/24 SAMAR, W. Coast – Lights
08(087)T/24 SAMAR, NE. Coast, Hiuinatungan I – Light
08(086)T/24 KALAYAAN ISLAND GROUP, Pag-asa Island – Buoy
07(074)T/24 PALAWAN, N. COAST, Cabuli I. – Light
07(073)T/24 LUZON, S. COAST, Sibuyan I – Lights
07(072)T/24 LUZON, NE. COAST – Lights
07(071)T/24 PHILIPPINE RISE, Benham Bank – Buoys
07(070)T/24 PALAWAN, N. COAST, Coron Passage – Buoys
07(069)T/24 LUZON, S. COAST, Sibuyan Island – Lights
07(068)T/24 LUZON, S. COAST, Laguna de Bay – Lights
07(067)T/24 LUZON, N. COAST, Batan Island – Light
07(066)T/24 LUZON, W. COAST, Manila Bay – Anchorage
07(065)T/24 LUZON, NE. COAST, Padsan River – Dredging
09(114)P/23 LUZON. S. COAST, Batangas Bay – Terminal
03(048)T/23 PALAWAN, E. COAST, off Miniloc Island – Buoy
03(047)T/23 BOHOL, W. COAST, Dawahon Bank – Light
02(032)T/23 PALAWAN, N. COAST, Coron Bay – Buoy
02(031)T/23 LUZON, W. COAST, Manila Bay – Buoy
01(020)T/23 LUZON, W. COAST, Manila Bay - Buoy
12(077)T/22 MASBATE, NORTH COAST, Masbate Harbor – Beacon
09(040)T/22 LUZON, W. COAST, Manila Bay – Buoy
07(032)T/22 LUZON, W. COAST, Manila Bay – Buoy
07(031)T/22 LUZON, W. COAST, Manila Bay – Buoy
05(022)T/22 LUZON, W. COAST, Manila Bay – Buoy
02(006)T/22 LUZON, W. COAST, Manila Bay – Buoys
04(023)P/19 MINDANAO, N. COAST, Iligan Bay – Buoy
02(014)P/17 MINDANAO, N. COAST, Butuan Bay – Submarine Pipeline

TABLE OF CONTENTS

Index of Charts Affected - - - - -	01
Chart Corrections - - - - -	02
Temporary & Preliminary Notices - - - - -	05
List of Lights Corrections - - - - -	06
Coast Pilot Corrections - - - - -	08
Navigational Warnings - - - - -	09
Publication Notices - - - - -	15

I

INDEX OF CHARTS AFFECTED

Chart No	Notice No.	Chart No	Notice No.	Chart No	Notice No.
1501	07(029)T/25	4447	07(027)T/25	PH2CVZ40	07(026)25
1518	07(026)25	4464	07(026)25	PH2SSA40	07(028)T/25
1539	07(026)25	4469	07(026)25	PH2NLZ40	07(029)T/25
1557	07(028)T/25	4705	07(029)T/25	PH4CBA40	07(027)T/25
1560	07(028)T/25	4706	07(029)T/25	PH4MCT40	07(029)T/25
4235	07(029)T/25	4707	07(028)T/25	PH5CBH40	07(027)T/25
4236	07(029)T/25	4726A	07(029)T/25	PH5MHR40	07(029)T/25
4243	07(029)T/25	5008	07(029)T/25	PH5TCBAN	07(026)25
4420	07(026)25	5009	07(028)T/25		
4426	07(027)T/25				

II

CHART CORRECTIONS

*07(026)25 – VISAYAS, E. Coast, Leyte Gulf, San Pedro Bay - Buoys

Chart 1518 2Ed 04/12/2011 Rev 11/29/2021 [WGS-84 DATUM] Last. NM 04(033)24

Insert		<i>Fl(2)G. 10s</i> "AMAN 1"	at	11°15.93'N 125°00.01'E
		<i>Fl(2)R. 10s</i> "AMAN 2"	at	11°15.97'N 125°00.21'E
		<i>Fl(2)G. 10s</i> "AMAN 3"	at	11°16.36'N 124°59.74'E
		<i>Q(3)10s</i> "AMAN E"	at	11°16.14'N 124°59.87'E
		<i>Q(6)+LFl. 15s</i> "AMAN H"	at	11°16.59'N 124°59.78'E

Chart 1539 1Ed 20/06/2019 [WGS-84 DATUM] Last NM. 08(083)24

Insert		<i>Fl(2)G. 10s</i> "AMAN 1"	at	11°15.93'N 125°00.01'E
		<i>Fl(2)R. 10s</i> "AMAN 2"	at	11°15.97'N 125°00.21'E
		<i>Fl(2)G. 10s</i> "AMAN 3"	at	11°16.36'N 124°59.74'E
		<i>Q(3)10s</i> "AMAN E"	at	11°16.14'N 124°59.87'E
		<i>Q(6)+LFl. 15s</i> "AMAN H"	at	11°16.59'N 124°59.78'E

Chart 4420 1Ed 11/1968 [Luzon Datum] Last NM. 10(120)23

Insert		<i>Fl(2)G. 10s</i> "AMAN 1"	at	11°16.00'N 124°59.92'E
		<i>Fl(2)R. 10s</i> "AMAN 2"	at	11°16.05'N 125°00.12'E
		<i>Fl(2)G. 10s</i> "AMAN 3"	at	11°16.43'N 124°59.65'E
		<i>Q(3)10s</i> "AMAN E"	at	11°16.22'N 124°59.79'E
		<i>Q(6)+LFl. 15s</i> "AMAN H"	at	11°16.66'N 124°59.70'E

Chart 4464 1Ed 01/6/1969 Rev 07/27/1981 [Luzon Datum] Last NM. 05(025)19

Insert		<i>Fl(2)G. 10s</i> "AMAN 1"	at	11°16'00.13"N 124°59'55.48"E
--------	---	--------------------------------	----	------------------------------

II

CHART CORRECTIONS

	<i>Fl(2)R.10s</i> "AMAN 2"	at	11°16'02.74"N 125°00'07.43"E
*07(026)25 – VISAYAS, E. Coast, Leyte Gulf, San Pedro Bay - Buoys (continued)			
	<i>Fl(2)G.10s</i> "AMAN 3"	at	11°16'25.85"N 124°59'39.19"E
	<i>Fl(2)R.10s</i> "AMAN 4"	at	11°16'23.46"N 124°59'49.02"E
	<i>Fl(2)G.10s</i> "AMAN 5"	at	11°16'31.29"N 124°59'40.84"E
	<i>Fl(2)R.10s</i> "AMAN 6"	at	11°16'29.23"N 124°59'48.56"E
	<i>Q(3)10s</i> "AMAN A"	at	11°16'05.08"N 124°59'53.50"E
	<i>Q(9)15s</i> "AMAN B"	at	11°16'07.88"N 125°00'03.53"E
	<i>Q(3)10s</i> "AMAN C"	at	11°16'09.54"N 124°59'48.76"E
	<i>Q(9)15s</i> "AMAN D"	at	11°16'13.90"N 124°59'52.54"E
	<i>Q(3)10s</i> "AMAN E"	at	11°16'13.05"N 124°59'47.32"E
	<i>Q(3)10s</i> "AMAN F"	at	11°16'17.04"N 124°59'43.53"E
	<i>Q(3)10s</i> "AMAN G"	at	11°16'21.73"N 124°59'40.21"E
	<i>Q(6)+LFl.15s</i> "AMAN H"	at	11°16'39.61"N 124°59'41.94"E
Chart 4469 1Ed 28/12/2017 [WGS-84 DATUM]			
Insert			
	<i>Fl(2)G.10s</i> "AMAN 1"	at	11°15'55.69"N 125°00'00.52"E
	<i>Fl(2)R.10s</i> "AMAN 2"	at	11°15'58.30"N 125°00'12.47"E
	<i>Fl(2)G.10s</i> "AMAN 3"	at	11°16'21.41"N 124°59'44.23"E
	<i>Fl(2)R.10s</i> "AMAN 4"	at	11°16'19.02"N 124°59'54.06"E
	<i>Fl(2)G.10s</i> "AMAN 5"	at	11°16'26.85"N 124°59'45.88"E

II

CHART CORRECTIONS

	<i>Fl(2)R.10s</i> "AMAN 6"	at	11°16'24.79"N 124°59'53.60"E
*07(026)25 – VISAYAS, E. Coast, Leyte Gulf, San Pedro Bay - Buoys (continued)			
	<i>Q(3)10s</i> "AMAN A"	at	11°16'00.64"N 124°59'58.54"E
	<i>Q(9)15s</i> "AMAN B"	at	11°16'03.44"N 125°00'08.57"E
	<i>Q(3)10s</i> "AMAN C"	at	11°16'05.10"N 124°59'53.80"E
	<i>Q(9)15s</i> "AMAN D"	at	11°16'09.46"N 124°59'57.58"E
	<i>Q(3)10s</i> "AMAN E"	at	11°16'08.61"N 124°59'52.36"E
	<i>Q(3)10s</i> "AMAN F"	at	11°16'12.60"N 124°59'48.57"E
	<i>Q(3)10s</i> "AMAN G"	at	11°16'17.29"N 124°59'45.25"E
	<i>Q(6)+LFl.15s</i> "AMAN H"	at	11°16'35.17"N 124°59'46.98"E

ENCs Affected: PH2CVZ40 and PH5TCBAN
(Philippine Coast Guard)

III

TEMPORARY AND PRELIMINARY NOTICES

***07(027)T/25 – CEBU, E. COAST, Cebu Harbor – Wreck**

1. A dangerous wreck was reported in 10° 18' 51" N, 123° 56' 13" E
2. Mariners are advised to navigate with caution in the area.
(WGS-84 Datum)

Charts affected: 4446, 4447

ENC affected: PH4CBA40, PH5CBH40

(Philippine Coast Guard)

***07(028)T/25 – PALAWAN, E. Coast. Sir John Brooke Point – Light**

Fl.R.5s, in position 08°46.17'N 117°49.68'E., is unlit.

Fl.G.5s, in position 08°46.18'N 117°49.60'E., is unlit.

(WGS84 DATUM)

Chart Affected: 1557, 1560, 4707, and 5009

ENC Affected: PH2SSA40

(Philippine Coast Guard)

***07(029)T/25 – LUZON, W. Coast, Pasig River – Light**

Pasig River Light, Fl.5s15m15M, in position 14°35.79'N 120°57.64'E., is unlit.

(WGS84 DATUM)

Chart Affected: 1501, 4235, 4236, 4243, 4705, 4706, 4726A, and 5008

ENC Affected: PH2NLZ40, PH4MCT40, PH5MHR40

(Philippine Coast Guard)

IV

LIST OF LIGHTS CORRECTIONS

LIGHTHOUSES

NUMBER (1)	NAME (2)	POSITION (3)	CHARACTERISTICS (4)	Elev(m) (5)	Range (NM) (6)	STRUCTURE (7)	REMARKS (8)	
REGION IV-A CALABARZON								
PALAWAN								
0560	F2160.2	BROOKE'S POINT JETTY Nr. 1	08 46 09.92 N 117 49 40.84E	Fl.G.5s		Concrete	TE 2025	
			*				*	
0561	F2160.5	BROOKE'S POINT JETTY Nr. 2	08 46 10.92 N 117 49 36.21E	Fl.R.5s		Concrete	TE2025	
			*				*	
NCR – NATIONAL CAPITAL REGION								
		PASIG RIVER	14 35 47.23 N 120 57 38.56 E	Fl.5s	15	15	Concrete, white round tower and dwelling, 14	TE 2025
0054	F2669							
			*				*	

LIGHTED BUOYS

NUMBER (1)	NAME (2)	POSITION (3)	CHARACTERISTICS (4)	Elev(m) (5)	Range (NM) (6)	STRUCTURE (7)	REMARKS (8)
EASTERN VISAYAS							
LEYTE							
	AMAN 1	11°15'55.69"N 125°00'00.52"E	Fl(2)G.10s			port-hand lateral mark, G. topmark: green cylinder	
	*	*	*			*	
	AMAN 2	11°15'58.30"N 125°00'12.47"E	Fl(2)R.10s			starboard-hand lateral mark, R. topmark: red cone, point up	
	*	*	*			*	
	AMAN 3	11°16'21.41"N 124°59'44.23"E	Fl(2)G.10s			port-hand lateral mark, G. topmark: green cylinder	
	*	*	*			*	
	AMAN 4	11°16'19.02"N 124°59'54.06"E	Fl(2)R.10s			starboard-hand lateral mark, R. topmark: red cone, point up	
	*	*	*			*	
	AMAN 5	11°16'26.85"N 124°59'45.88"E	Fl(2)G.10s			port-hand lateral mark, G. topmark: green cylinder	
	*	*	*			*	
	AMAN 6	11°16'24.79"N 124°59'53.60"E	Fl(2)R.10s			starboard-hand lateral mark, R. topmark: red cone, point up	
	*	*	*			*	
	AMAN A	11°16'00.64"N 124°59'58.54"E	Q(3)10s			east cardinal mark, BYB. topmark: 2 cones, base to base	
	*	*	*			*	
	AMAN B	11°16'03.44"N 125°00'08.57"E	Q(9)15s			west cardinal mark, YBY. topmark: 2 cones, point to point	
	*	*	*			*	
	AMAN C	11°16'05.10"N 124°59'53.80"E	Q(3)10s			east cardinal mark, BYB. topmark: 2 cones, base to base	
	*	*	*			*	
	AMAN D	11°16'09.46"N 124°59'57.58"E	Q(9)15s			west cardinal mark, YBY.	

IV

LIST OF LIGHTS CORRECTIONS

	*	*	*	topmark: 2 cones, point to point *
AMAN E	*	11°16'08.61"N 124°59'52.36"E	Q(3)10s	east cardinal mark, BYB. topmark: 2 cones, base to base *
AMAN F	*	11°16'12.60"N 124°59'48.57"E	Q(3)10s	east cardinal mark, BYB. topmark: 2 cones, base to base *
AMAN G	*	11°16'17.29"N 124°59'45.25"E	Q(3)10s	east cardinal mark, BYB. topmark: 2 cones, base to base *
AMAN H	*	11°16'35.17"N 124°59'46.98"E	Q(6)+LFl.15s	south cardinal mark, YB. topmark: 2 cones, point down *

Note: Asterisk () indicates new information in the column above it. Positions given are approximate and in WGS84 Datum unless otherwise stated in column 8.*

V

COAST PILOT CORRECTIONS

Philippine Coast Pilot, 8th Ed. Volume I-B

Chapter 10 – SAMAR ISLAND

Page 10-30, left column, line 14.

Insert:

Navigational Aids – Navigational buoys were laid in the San Juanico Strait to guide vessels entering the government pier.

VI

NAVIGATIONAL WARNINGS

*See all active Navigational Warnings at
<https://staging.geoportal.gov.ph/nwapp/>*

NAVPHIL 272/24

SAMAR SEA.

CALBAYOG CITY.

CHART 1539.

LIGHTBUOYS 12-02.58N 124-35.45E AND 12-03.35N 124-35.75E UNLIT.

NAVPHIL 293/24

BUTUAN BAY.

LA UNION PT, SW.

CHART 1536.

SUBMERGED MOORING BUOY REPORTED
09-04.29N 125-31.05E.

NAVPHIL 305/24

CALAMIAN GROUP.

CORON PASSAGE.

CHART 1553.

PORT HAND LIGHTBUOY 11-59.30N 120-14.73E MISSING.

NAVPHIL 307/24

MANILA BAY.

MANILA SOUTH HARBOR.

CHART 4243.

LIGHTBUOY, NNSL 8, 14-34.26N 120-54.64E

OFF STATION TO 14-34.28N

120-54.62E.

NAVPHIL 351/24.

LUZON SEA.

PINGET I, W.

CHART 1504.

PINGET LIGHT, 17-41.33N 120-21.25E, F2715,
UNLIT.

NAVPHIL 361/24

VERDE ISLAND PASSAGE.

CAPE SANTIAGO.

CHART 1564.

CAPE SANTIAGO LIGHT, 13-46.32N 120-39.18E, F2614, UNLIT.

NAVPHIL 362/24

PHILIPPINE SEA.

MINDANAO, E.

CHART 2200.

SUBMARINE CABLE REPAIRING WORKS BY
C/S ILE DE BREHAT, IN PROGRESS
UNTIL FURTHER NOTICE, IN VICINITY OF
LINE JOINING:

08-21.00N 130-02.00E

08-33.00N 130-12.00E

08-45.00N 130-25.00E.

NAVPHIL 363/24

PALAWAN, E.

GREEN ISLAND BAY.

CHART 1562.

BARBACAN LIGHT, 10-19.10N 119-21.01E,
F2169.5, UNLIT.

NAVPHIL 386/24

MACAJALAR BAY.

MACABALAN PORT.

CHART 4646.

MACABALAN LIGHT, 08-30.42N 124-39.70E,
F2266, UNLIT.

NAVPHIL 015/25

PALAWAN.

IPOLETE BAY.

CHART 1557.

BROOKES POINT LIGHTBUOYS

ESTABLISHED.

A. PORT HAND 8-45.90N 117-49.30E.

B. STARBOARD HAND 8-45.78N 117-49.86E.

C. PORT HAND 8-46.19N 117-49.44E.

D. STARBOARD HAND 8-46.12N 117-49.77E.

E. SPECIAL 8-46.13N 117-49.64E.

NAVPHIL 016/25

PALAWAN.

CORON BAY.

CHART 1553.

CULION LIGHTBUOYS ESTABLISHED.

A. PORT HAND 11-53.50N 120-2.23E.

B. STARBOARD HAND 11-54.13N 120-2.19E.

C. PORT HAND 11-53.72N 120-1.41E.

D. STARBOARD HAND 11-54.02N 120-1.35E.

E. SOUTH CARDINAL 11-54.75N 120-4.28E.

F. SOUTH CARDINAL 11-54.29N 120-3.52E.

G. ISOLATED DANGER 11-53.72N 120-3.60E.

NAVPHIL 017/25

PALAWAN.

BACUIT BAY.

CHART 4341.

EL NIDO LIGHTBUOYS ESTABLISHED.

A. PORT HAND 11-11.20N 119-23.10E.

B. STARBOARD HAND 11-11.20N 119-23.04E.

C. PORT HAND 11-11.09N 119-23.21E.

D. STARBOARD HAND 11-11.06N 119-23.18E.

E. ISOLATED DANGER 11-11.21N 119-21.45E.

F. SOUTH CARDINAL 11-11.82N 119-21.78E.

G. NORTH CARDINAL 11-11.14N 119-22.51E.

H. NORTH CARDINAL 11-11.30N 119-22.74E.

I. SOUTH CARDINAL 11-11.87N 119-22.54E.

J. EAST CARDINAL 11-12.53N 119-22.86E.

K. EAST CARDINAL 11-11.90N 119-22.92E.

L. NORTH CARDINAL 11-11.36N 119-22.90E.

M. WEST CARDINAL 11-11.36N 119-23.08E.

N. WEST CARDINAL 11-11.00N 119-23.25E.

NAVPHIL 018/25

VI

NAVIGATIONAL WARNINGS

PALAWAN.

PUERTO PRINCESA HARBOR.

CHART 1555.

PUERTO PRINCESA LIGHTBUOYS
ESTABLISHED.

- A. PORT HAND 9-42.30N 118-45.68E.
- B. STARBOARD HAND 9-42.77N 118-45.75E.
- C. PORT HAND 9-42.64N 118-44.86E.
- D. STARBOARD HAND 9-43.08N 118-44.97E.
- E. PORT HAND 9-42.91N 118-44.20E.
- F. STARBOARD HAND 9-43.38N 118-44.26E.
- G. NORTH CARDINAL 9-44.37N 118-43.20E.
- H. NORTH CARDINAL 9-44.58N 118-43.26E.
- I. NORTH CARDINAL 9-44.79N 118-43.81E

NAVPHIL 019/25

PALAWAN.

BARBACAN PT, S.

CHART 1555.

ROXAS LIGHTBUOYS ESTABLISHED.

- A. PORT HAND 10-13.60N 119-20.30E.
- B. STARBOARD HAND 10-13.74N 119-21.23E.
- C. PORT HAND 10-14.79N 119-20.23E.
- D. STARBOARD HAND 10-14.81N 119-21.12E.
- E. PORT HAND 10-16.40N 119-20.10E.
- F. STARBOARD HAND 10-16.44N 119-20.92E.
- G. WEST CARDINAL 10-13.20N 119-21.31E.
- H. WEST CARDINAL 10-17.56N 119-20.80E.
- I. WEST CARDINAL 10-18.33N 119-20.67E.

NAVPHIL 020/25

PALAWAN.

TAYTAY HARBOR.

CHART 1554.

TAYTAY LIGHTBUOYS ESTABLISHED.

- A. PORT HAND 10-48.23N 119-36.08E.
- B. STARBOARD HAND 10-48.34N 119-36.18E.
- C. PORT HAND 10-48.36N 119-35.71E.
- D. STARBOARD HAND 10-48.53N 119-35.79E.
- E. EAST CARDINAL 10-47.86N 119-36.49E.
- F. EAST CARDINAL 10-48.55N 119-35.56E.

NAVPHIL 022/25

SAN MIGUEL BAY.

CHART 1514.

- 1. HYDROGRAPHIC SURVEY IN PROGRESS
UNTIL 31 JUL 2025 BY MB
ABSD, 10 TONS, IN AREA BOUND BY
14-02.12N 123-06.83E
14-02.45N 123-09.70E
14-01.58N 123-12.47E
13-58.08N 123-13.87E
13-55.62N 123-17.62E
13-49.00N 123-19.43E
13-43.67N 123-12.95E
13-46.45N 123-02.82E
13-52.45N 123-03.97E
13-59.02N 123-04.87E.
WIDE BERTH REQUESTED.

- 2. CANCEL THIS MSG 01 AUG 2025.

NAVPHIL 043/25

LUZON SEA.

CHART 1504.

- 1. DREDGING ACTIVITY IN PROGRESS UNTIL
31 DEC 2025 BY MV DE XIN 7 IN
THE AREA BOUND BY
17-30.47N 120-23.03E,
17-29.96N 120-22.16E,
17-28.66N 120-22.98E,
17-28.74N 120-23.10E,
17-28.19N 120-23.85E,
17-28.20N 120-24.72E,
17-29.17N 120-24.72E,
17-29.17N 120-23.84E.
- 2. CANCEL THIS MSG 01 JAN 2026.

NAVPHIL 044/25

LUZON SEA.

ABRA R.

CHART 1504.

- 1. DREDGING ACTIVITY IN PROGRESS UNTIL
31 DEC 2025 BY MV DE XIN 7 IN
THE AREA BOUND BY
17-30.19N 120-23.33E,
17-30.49N 120-23.19E,
17-33.61N 120-27.18E,
17-30.77N 120-25.00E.
- 2. CANCEL THIS MSG 01 JAN 2026.

NAVPHIL 053/25

MINDORO I, W.

APO EAST PASS.

CHART 4726A

- 1.DREDGING OPERATIONS IN PROGRESS
UNTIL 04 DEC 2025 BY DEXIN 7,LIANG KU 9,
LIANG KU 99, HONG KU 588, HONG FU 598,
HENG DA 188,HENG DA 988, FENG SHOU 178,
TAI SHUN 88, HONG FU 518, LIANG KU88,
LIANG KU 89, JIN HAI FU 168, ZHONG XING
HANG 268, HONG FU558, HENG DA 17, HENG
DA 19, HONG FA 158, HONG FA 178, HUI
JINQIAO 139, XIANG HANG 555, HONG FA 567,
RUN TAI ZHI HANG, HENG DA99, HONG HAI
199, HONG HAI 16, AND YONG XIN 1 IN THE
AREA BOUNDBY
12-54.64N 120-44.36E, 12-57.20N 120-43.72E,
12-57.72N 120-46.16E, 12-56.64N 120-46.25E,
12-57.04N 120-46.88E, 12-56.98N 120-46.96E,
12-56.33N 120-46.34E, 12-55.23N 120-46.75E.
- 2.WIDE BERTH REQUESTED.
- 3.CANCEL THIS MSG 05 DEC 2025

NAVPHIL 065/25

LAMON BAY.

PORT ALABAT.

CHART 1513.

VI

NAVIGATIONAL WARNINGS

ALABAT PORT LIGHT 14-05.93N 122-055E
TEMPORARILY REMOVED.

NAVPIL 078/25

MANILA BAY.

CHART 1501.

1. SCIENTIFIC OPERATIONS IN PROGRESS
UNTIL 30 SEPT 2025 BY MTUG
SEASTRENGTH ONE AND BARGE
STONWORKS 203 IN VICINITY LINES
JOINING:

14-33.08N 120-57.70E, 14-33.07N 120-57.72E,
14-33.05N 120-57.74E, 14-33.04N 120-57.76E,
14-33.02N 120-57.77E.

WIDE BERTH REQUESTED.

2. CANCEL THIS MSG 01 OCT 2025.

NAVPIL 079/25

MANILA BAY.

SANGLEY PT, NE.

CHART 1501.

1. DREDGING OPERATIONS IN PROGRESS
UNTIL 25 AUG 2025 BY HANGBU 3001 AND JIN
XIN 23 IN THE AREA BOUND BY

14-33.55N 120-58.64E, 14-31.62N 120-58.75E,
14-31.57N 120-57.58E, 14-31.69N 120-57.14E,
14-31.66N 120-54.20E, 14-32.04N 120-54.20E,
14-32.07N 120-57.14E, 14-33.01N 120-57.24E,
14-33.42N 120-58.17E.

WIDE BERTH REQUESTED.

2. CANCEL THIS MSG 26 AUG 2025.

NAVPIL 080/25

MANILA BAY.

CHART 1501.

1. DREDGING OPERATIONS IN PROGRESS
UNTIL 31 DEC 2025 BY MV SILK ROAD 13 IN
THE AREA BOUND BY

14-37.72N 120-56.77E, 14-37.75N 120-56.77E,
14-37.77N 120-57.40E, 14-37.76N 120-57.42E,
14-37.59N 120-57.57E, 14-37.57N 120-57.57E,
14-37.58N 120-57.55E, 14-37.71N 120-57.43E,
14-37.70N 120-57.43E, 14-37.73N 120-57.40E,
14-37.74N 120-57.39E.

WIDE BERTH REQUESTED.

2. CANCEL THIS MSG 01 JAN 2026.

NAVPIL 104/25

PALAWAN PASSAGE.

TAPIUTAN I, NW.

CHART 1563.

1. SCIENTIFIC OPERATIONS BY NOBLE
VIKING FROM 15 MAY TO 14 OCT 2025 IN: A.
11-38.23N 118-56.36E B. 11-34.11N 118-53.54E
C. 11-48.76N 118-57.68E

2. CANCEL THIS MSG 15 OCT 2025.

NAVPIL 105/25

MANILA BAY.

LIMAY PT, E.

CHART 4250.

1. WRECK REMOVAL OPERATIONS IN
PROGRESS 14-30.32N 120-40.46E. A
TEMPORARY EXCLUSION ZONE RADIUS
THREE NAUTICAL MILES HAS BEEN
ESTABLISHED CENTERED ON THIS
POSITION.

2. SHIPS ARE PROHIBITED FROM ENTERING
OR REMAINING WITHIN THIS ZONE.

NAVPIL 107/25

MANILA BAY.

SANGLEY PT, NE.

CHART 1501.

1. DREDGING OPERATIONS IN PROGRESS
UNTIL 17 SEPT 2025 BY BKS 292, BKM 102,
BARGE AST1805 AND TUG SKUA IN AREA
BOUND BY 14-31.80N 120-53.70E, 14-31.96N
120-53.67E,

14-32.90N 120-55.52E, 14-33.58N 120-55.51E,
14-33.57N 120-55.93E, 14-33.56N 120-56.94E,
14-33.55N 120-58.14E, 14-33.07N 120-58.14E,
14-32.80N 120-57.56E, 14-32.44N 120-56.79E,
14-32.14N 120-56.16E, 14-32.19N 120-55.85E,
14-32.33N 120-55.52E.

WIDE BERTH REQUESTED.

2. CANCEL THIS MSG 18 SEPT 2025.

NAVPIL 146/25

LAGONUY GULF.

MAQUEDA CHANNEL.

CHART 1514.

1. CABLE LAYING OPERATIONS IN
PROGRESS UNTIL 30 JUL 2025 BY CS FU HAI
ALONG LINES JOINING:

13-36.06N 124-05.32E, 13-35.06N 124-03.51E,
13-34.97N 123-59.37E, 13-35.54N 123-57.07E,
13-37.29N 123-54.89E, 13-40.68N 123-52.66E,
13-44.18N 123-52.10E.

WIDE BERTH REQUESTED.

2. CANCEL THIS MSG 31 JUL 2025.

NAVPIL 147/25

BABUYAN CHANNEL TO LUZON SEA.

LUZON I, N TO W.

CHART 4705.

1. CABLE LAYING OPERATIONS IN
PROGRESS UNTIL 30 JUL 2025 BY CS FU HAI
ALONG LINES JOINING:

A. 18-36.40N 121-04.03E, 18-39.29N 121-
05.49E,
18-40.70N 121-07.62E, 18-41.04N 121-10.65E,
18-40.64N 121-15.32E, 18-39.94N 121-18.10E,
18-37.75N 121-21.59E, 18-31.10N 121-28.80E,
18-28.80N 121-30.25E, 18-25.05N 121-30.59E.
B. 17-57.62N 120-28.48E, 17-59.05N 120-
26.65E,
18-06.55N 120-22.27E, 18-09.36N 120-21.47E,

VI

NAVIGATIONAL WARNINGS

18-10.94N 120-22.18E, 18-14.72N 120-21.96E,
18-24.41N 120-23.70E, 18-33.61N 120-28.55E,
18-38.14N 120-33.28E, 18-40.64N 120-39.49E,
18-42.30N 120-41.54E, 18-42.95N 120-43.20E,
18-42.79N 120-51.75E, 18-41.98N 120-55.23E,
18-42.23N 120-59.59E, 18-41.50N 121-01.37E,
18-39.23N 121-04.52E, 18-36.39N 121-04.03E.
C. 16-51.62N 120-22.70E, 16-53.48N 120-
20.70E,
16-55.59N 120-20.14E, 16-57.50N 120-20.19E,
16-59.50N 120-20.96E, 17-00.72N 120-20.95E,
17-05.61N 120-23.26E, 17-07.97N 120-23.37E,
17-13.90N 120-22.27E, 17-17.27N 120-22.84E,
17-21.37N 120-24.78E, 17-23.50N 120-24.06E,
17-26.15N 120-24.89E, 17-26.95N 120-24.20E,
17-27.82N 120-24.16E, 17-29.59N 120-22.55E,
17-30.70N 120-19.96E, 17-32.97N 120-17.45E,
17-35.98N 120-12.39E, 17-37.75N 120-11.35E,
17-40.52N 120-11.13E, 17-49.71N 120-13.69E,
17-54.44N 120-17.19E, 17-56.37N 120-20.64E,
17-57.62N 120-28.48E.
D. 15-53.07N 119-53.56E, 15-54.24N 119-
50.84E,
15-53.82N 119-47.73E, 15-55.00N 119-40.43E,
15-55.79N 119-38.72E, 15-57.35N 119-37.48E,
15-59.75N 119-36.14E, 16-02.36N 119-35.78E,
16-11.44N 119-36.82E, 16-20.10N 119-36.51E,
16-21.51N 119-37.19E, 16-22.53N 119-38.14E,
16-24.75N 119-38.99E, 16-26.79N 119-41.38E,
16-28.19N 119-43.95E, 16-30.61N 119-45.89E,
16-45.05N 120-03.04E, 16-47.52N 120-04.67E,
16-48.18N 120-05.56E, 16-48.45N 120-06.72E,
16-50.69N 120-10.27E, 16-51.27N 120-14.21E,
16-52.23N 120-16.83E, 16-52.30N 120-20.12E,
16-51.62N 120-22.70E.
E. 15-03.65N 120-03.64E, 15-04.03N 120-
01.61E,
15-07.24N 119-58.11E, 15-10.17N 119-57.12E,
15-12.36N 119-57.29E, 15-14.69N 119-58.67E,
15-16.24N 119-58.14E, 15-17.54N 119-56.11E,
15-18.78N 119-49.69E, 15-24.92N 119-43.56E,
15-30.01N 119-41.98E, 15-43.15N 119-40.38E,
15-46.46N 119-41.22E, 15-50.51N 119-45.64E,
15-52.51N 119-48.62E, 15-52.80N 119-49.85E,
15-52.35N 119-52.73E, 15-53.07N 119-53.56E.
WIDE BERTH REQUESTED.
2. CANCEL THIS MSG 31 JUL 2025.

NAVPIL 148/25
PHILIPPINE SEA.
BENHAM BANK.
CHART 5002.

LIGHTBUOYS:

A. 15-47.42N 124-16.03E, DESTROYED.
B. 15 47.48N 124 18.53E, DESTROYED.
C. 15-50.57N 124-16.33E, DESTROYED.

NAVPIL 150/25
BABUYAN CHANNEL

LUZON I, N.

CHART 1505.

1. SCIENTIFIC OPERATIONS BY CS VEGA IN
PROGRESS UNTIL 09 AUG 2025 IN AREA
BOUND BY

18-29.46N 121-34.52E, 18-33.36N 121-30.79E,
18-43.10N 121-04.78E.

WIDE BERTH REQUESTED.

2. CANCEL THIS MSG 10 AUG 2025.

NAVPIL 157/25

LUZON SEA TO WEST PHILIPPINE SEA.

LUZON I, W

CHART 2200.

1.

CABLE LAYING OPERATIONS BY CS
NUSANTARA EXPLORER IN PROGRESS
UNTIL 02 AUG 2025 ALONG LINES JOINING:

A. 16-51.62N 120-22.70E, 16-52.14N 120-
22.30E,

16-52.31N 120-22.02E, 16-52.33N 120-21.83E,
16-52.79N 120-21.14E, 16-52.85N 120-20.90E,
16-52.90N 120-19.85E, 16-53.78N 120-15.95E,
16-53.91N 120-11.55E, 16-53.24N 120-07.95E,
16-53.15N 119-57.32E, 16-53.44N 119-55.49E,
16-55.34N 119-52.38E, 16-55.55N 119-50.73E,
16-55.56N 119-47.54E, 16-59.13N 119-35.00E,
16-58.46N 119-26.78E, 16-58.89N 119-19.46E,
17-01.02N 119-14.75E, 17-04.07N 118-51.98E,
16-56.52N 118-21.75E, 16-56.23N 118-15.98E,
16-59.02N 118-04.39E, 16-59.49N 117-26.43E,
16-55.43N 117-04.86E, 16-55.61N 116-55.61E,
16-57.83N 116-50.90E, 17-06.73N 116-43.08E,
17-09.31N 116-37.84E, 17-11.63N 116-29.86E,
17-11.10N 116-20.81E, 17-00.83N 115-54.55E,
16-55.09N 115-48.60E.

B. 16-32.56N 120-19.14E, 16-31.24N 120-
16.34E,

16-31.18N 120-15.96E, 16-31.29N 120-15.39E,
16-31.46N 120-15.07E, 16-32.15N 120-13.25E,
16-32.38N 120-12.48E, 16-32.89N 120-11.13E,
16-32.94N 120-10.77E, 16-32.95N 120-10.37E,
16-33.28N 120-09.52E, 16-33.77N 120-08.71E,
16-34.17N 120-07.83E, 16-34.63N 120-06.60E,
16-34.74N 120-06.13E, 16-34.93N 120-05.79E,
16-34.99N 120-05.54E, 16-35.14N 120-05.28E,
16-35.19N 120-05.06E, 16-35.23N 120-04.62E,
16-35.41N 120-03.69E, 16-35.61N 120-03.23E,
16-35.67N 120-03.01E, 16-35.69N 120-02.73E,
16-35.63N 120-02.32E, 16-35.63N 120-01.27E,
16-35.55N 120-00.73E, 16-35.52N 119-58.63E,
16-35.59N 119-54.72E, 16-35.36N 119-50.00E,
16-34.86N 119-47.90E, 16-34.87N 119-46.82E,
16-35.34N 119-45.06E, 16-35.35N 119-43.80E,
16-34.18N 119-36.25E, 16-28.55N 119-21.79E,
16-28.48N 119-13.17E, 16-27.81N 119-08.14E,
16-28.26N 119-02.87E, 16-32.69N 118-52.81E,
16-34.44N 118-44.05E, 16-37.63N 118-38.12E,
16-41.69N 118-32.84E, 16-43.91N 118-26.73E,

VI

NAVIGATIONAL WARNINGS

16-43.73N 118-21.43E, 16-41.24N 118-10.54E,
16-40.41N 117-54.96E, 16-39.50N 117-53.19E,
16-35.87N 117-50.55E, 16-30.74N 117-41.75E,
16-28.40N 117-30.35E, 16-24.28N 117-22.68E,
16-20.12N 116-46.41E, 16-17.86N 116-42.30E,
16-10.73N 116-33.66E, 16-08.68N 116-29.47E,
16-07.03N 116-06.63E, 16-04.87N 116-02.16E,
15-58.21N 115-56.01E.

WIDE BERTH REQUESTED.

2. CANCEL THIS MSG 03 AUG 2025.

NAVPIL 159/25

MANILA BAY.

PASAY.

CHART 1501.

DREDGING OPERATIONS IN PROGRESS BY
JIN XIN 709 IN AREA BOUND BY
14-33.54N, 120-58.64E, 14-31.62N, 120-58.75E,
14-31.63N, 120-57.58E, 14-31.69N, 120-57.14E,
14-32.07N, 120-57.14E, 14-33.01N, 120-57.24E,
14-33.42N, 120-58.17E.

NAVPIL 160/25

LUZON SEA

CHART 1501.

DREDGING OPERATIONS IN PROGRESS BY
MV SANKO UNO 68 AND DREDGE MASTER 5
IN AREAS BOUND BY:

A.

14-25.88N 120-23.98E, 14-27.04N 120-24.63E,
14-26.35N 120-25.39E, 14-26.26N 120-27.21E,
14-24.86N 120-26.59E, 14-25.39N 120-24.94E.

B.

14-27.42N 120-22.09E, 14-28.36N 120-21.71E,
14-29.93N 120-21.44E, 14-30.05N 120-22.57E,
14-28.41N 120-22.85E, 14-28.02N 120-23.07E.

NAVPIL 166/25

BURIAS PASS.

PORT PIO DURAN.

CHART 1541.

1. HYDROGRAPHIC SURVEY 24 JUN TO 31
JUL 2025 IN AREA BOUND BY

123-24.57E 13-0.45N, 123-24.57E 13-2.50N,
123-27.62E 13-2.50N, 123-27.62E 13-0.45N.

2. CANCEL THIS MSG 01 AUG 2025.

NAVPIL 174/25

LUZON SEA.

SANTO TOMAS R, W.

CHART 1502.

DREDGING OPERATIONS IN PROGRESS BY
MV HONG FA 569 IN AREA BOUND BY
15-02.55N 120-02.71E, 15-02.58N 120-03.16E,
15-01.76N 120-03.38E, 15-01.75N 120-02.73E.

NAVPIL 175/25

MANILA BAY.

PASAY CITY.

CHART 1501.

DREDGING OPERATIONS IN PROGRESS BY
MV HONG FA 569 IN AREA BOUND BY
14-33.23N 120-57.10E, 14-33.28N 120-57.10E,
14-33.28N 120-57.66E, 14-33.24N 120-57.66E.

NAVPIL 179/25

SAMAR SEA.

BILIRAN I, E AND W.

CHART 1539.

1. SCIENTIFIC OPERATIONS FROM 11 JUL TO
08 AUG 2025 IN AREAS BOUND BY:

A. 11-44.03N 124-22.78E, 11-46.98N 124-
28.04E,

11-46.04N 124-28.58E, 11-46.58N 124-29.54E,
11-45.64N 124-30.09E, 11-46.44N 124-31.52E,
11-43.62N 124-33.16E, 11-43.88N 124-33.64E,
11-29.27N 124-42.08E, 11-25.52N 124-35.39E,
11-27.40N 124-34.30E, 11-29.28N 124-37.65E,
11-29.75N 124-37.37E, 11-30.56N 124-38.81E,
11-41.87N 124-32.27E, 11-41.60N 124-31.79E,
11-42.07N 124-31.52E, 11-41.80N 124-31.04E,
11-42.27N 124-30.77E, 11-42.00N 124-30.29E,
11-42.47N 124-30.02E, 11-42.21N 124-29.54E,
11-43.15N 124-28.99E, 11-42.88N 124-28.52E,
11-43.35N 124-28.24E, 11-42.81N 124-27.29E,
11-43.28N 124-27.01E, 11-42.75N 124-26.06E,
11-43.22N 124-25.79E, 11-42.68N 124-24.83E,
11-43.15N 124-24.56E, 11-42.61N 124-23.60E.

B. 11-35.67N 124-22.33E, 11-34.80N 124-
22.99E,

11-34.48N 124-22.55E, 11-34.04N 124-22.88E,
11-33.88N 124-22.66E, 11-28.23N 124-26.93E,
11-27.58N 124-26.05E, 11-34.54N 124-20.79E.

WIDE BERTH REQUESTED.

2. CANCEL THIS MSG 09 AUG 2025.

NAVPIL 183/25

LUZON SEA.

ABRA R.

CHART 1504.

DREDGING OPERATIONS IN PROGRESS BY
MV YONG XIN 1 IN AREAS BOUND BY:

A. 17-30.77N 120-24.98E, 17-30.19N 120-
23.33E,

17-30.49N 120-23.19E, 17-33.61N 120-27.18E.
B. 17-30.47N 120-23.03E, 17-29.17N 120-
23.84E,

17-29.17N 120-24.72E, 17-28.20N 120-24.72E,
17-28.19N 120-23.85E, 17-28.74N 120-23.10E,
17-28.66N 120-22.97E, 17-29.96N 120-22.16E.

NAVPIL 191/25

PHILIPPINE SEA.

LUZON I, N TO NE.

CHART 4705.

1. SCIENTIFIC OPERATIONS BY MTUG SEDAR
10 IN PROGRESS UNTIL 31 AUG 2025 ALONG
A LINE JOINING

VI

NAVIGATIONAL WARNINGS

18-41.77N 121-10.87E, 18-44.52N 122-16.53E,
19-04.22N 122-56.42E, 19-41.60N 123-26.23E,
20-24.62N 123-28.26E, 21-17.99N 123-24.43E,
21-32.49N 123-11.74E.

WIDE BERTH REQUESTED.

2. CANCEL THIS MSG 01 SEPT 2025.

NAVPHIL 193/25

SULU SEA.

CHART 1528.

1. CABLE LAYING OPERATIONS IN
PROGRESS UNTIL 31 JUL 2025 IN AREA
BOUND BY

07-06.50N 121-51.00E, 07-06.50N 121-54.50E,
07-04.00N 121-54.50E, 07-04.00N 121-51.00E.

WIDE BERTH REQUESTED.

2. CANCEL THIS MSG 01 AUG 2025.

NAVPHIL 195/25

BALAYAN BAY.

CHART 1564.

1. DREDGING OPERATIONS IN PROGRESS
UNTIL 16 AUG BY ROYAL HARBOUR AND
MTUG STA CRUZ BRIDGE IN AREA BOUND BY

13-54.22N 120-50.97E, 13-54.33N 120-50.78E,
13-54.44N 120-50.83E, 13-54.47N 120-50.96E,
13-54.54N 120-50.98E, 13-54.53N 120-51.04E.

2. CANCEL THIS MSG 17 AUG 2025.

VII

PUBLICATION NOTICES

There is no publication notice for this month.

NAMRIA BULLETIN

1. Mariners are requested to notify the Hydrography Branch, NAMRIA of any changes or discrepancies found on Nautical charts and Nautical publications issued by this office, especially if this affects navigational safety in Philippine Waters. The information may be sent using the Hydrographic Note found at <https://namria.gov.ph/omsis/HNote10.aspx>.
2. Clients may purchase maps, nautical charts, publications, and other maritime products online at <https://namria.gov.ph/eMapa>.
3. Please be advised that effective in October 2023, in alignment with Civil Service Commission Memorandum Circular numbers 22, series of 2014 and 6, series of 2022, and in support of the Department of Energy's energy-efficiency initiatives, we are implementing remote-work practice for non-frontline personnel every Friday. Frontline personnel engaged in critical functions and services will maintain their onsite presence.
4. Frontline personnel can be reached through the following contact numbers: Taguig City, Fort Bonifacio Map Sales Office (MSO) - (02) 8810-4831 to 42 at local 431, (02) 8810-5467, 0956 5587584, and 0915 2777903; San Nicolas, Manila MSO - (02) 8245-9498, (02) 8241-3494 at local 117, 0966 8523814, and 0921 3627524; DENR-Visayas Avenue (MSO) - 0999 6079193 and 0928 4497159; and Client Service Section - css.gismb@namria.gov.ph and 02 88875466.

Nautical Charts, Topographic Maps, Tide and Current Tables, and related publications are available for sale at the NAMRIA Map Sales Offices (MSO). Nautical Charts can also be purchased online through <https://namria.gov.ph/eMapa/>

Region	Address	MSO STAFF	Phone/Fax
Main	Lawton Avenue, Fort Andres Bonifacio, Taguig City	Michelle Ann M. Aguilar Ana Victoria A. Labor Marlon Y. Aguilar	(02) 8810-4831 to 42 loc 431 (02) 8810-5467 0956 5587584 0915 2777903
NCR	421 Barraca Street, San Nicolas, Binondo, Manila	SN3 Marilou B. Cinco Romeo B. Brizuela Mary Jane M. Montano	(02) 8245-9498 (02) 8241-3494 loc 117 0966 8523814
NCR	FMB Building DENR Compound, Visayas Avenue, Quezon City	Sherry Ann S. Perez Glenn M. De Jesus	0999 6079193 0928 4497159
I	DENR Government Center, Sevilla City, San Fernando, La Union	Ayessa A. Valencia	0905 3443202
II	DENR-Land Evaluation Party Building II, Brgy. Carig, Tuguegarao City	Rubilyn T. Pulpulaan	0917 6519625
III	DENR Compound, Diosdado, Macapagal Gov't. Center. Maimpis City, San Fernando, Pampanga	Rosalina M. Libunao	0991 3509756
IVA	Provincial Planning and Development Office, Capitol Complex, Batangas City	Engr. Leda P. Velasquez	0961 4552583
IVB	DENR-PENRO Santa Monica, Puerto Princesa City	Juvy B. Sarmiento Corazon L. Zeñarosa	0916 203 8041
V	DENR-Operation/Survey Division, Rizal Street, Sagpon, Legaspi City, Albay	Isabelita T. Climaco	0906 3363033
VI	Manuel Lagunilla Bldg., DENR Compound, Parola, Iloilo City	Temporarily Closed	
VII	DENR-CENRO Building, Arellano Boulevard corner V. Sotto Street Pier 3, Cebu City	Melchor Togonon Renato B. Alcontin, Jr.	0922 7910372 0931 0010341 0961 4552579
VIII	DENR Compound, Santo Niño Extension, Tacloban City	Temporarily Closed	
IX	Pres. Corazon C. Aquino Regional Government Center, Balintawak, Pagadian City, Zamboanga Del Sur	Ednalyn C. Macahidhid	0955 5826075 0948 2943647
IX	DENR CENRO, West General Vicente Alvarez St., Zone 4, Zamboanga City	Annete P. Flores	0955 8928777
X	DENR Building Macabalan, Cagayan de Oro City, Misamis Oriental	Temporarily Closed	

XI	Kilometer 7, SPED Road, Bangkal, Davao City	<i>Temporarily Closed</i>	
XII	3rd Floor, DENR Building Land Evaluation Survey Section, Aurora Street, Barangay Zone IV Koronadal City, South Cotabato	Jeanyluz B. Bautista	0909 9324745
CARAGA	DENR - Land Management Services Building, Ambago, Butuan City, Agusan del Norte	Maricar E. Siega	0948 3619452